

FASTTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

NEW H5100701

NOT APPROVED
17/12/20
H/S \$5700

4 days

VEHICLE No: SJW 7575Y

1PC	TAILGATE	NEC 82.00	\$1,820.00	X
1PC	TAILGATE REAR LOGO	NEC 68.00	\$105.00	/
1PC	TAILGATE 'FOCUS' EMBLEM	NEC 90.00	\$88.00	/
1PC	TAILGATE 'TITANIUM' EMBLEM	NEC 322.00	\$102.00	/
1PC	TAILGATE WEATHERSTRIP	SVC	\$385.00	/
1PC	TAILGATE INNER LOCK	DO/NE 1320	\$399.00	X
1PC	REAR BUMPER	2e/7000 685	\$1,650.00	/
1PC	REAR BUMPER LOWER	304 755	\$980.00	/
1PC	REAR BUMPER REINFORCEMENT	CNE 350	\$985.00	/
1PC	REAR BUMPER TOP RETAINER	SVC	\$499.00	/
1PC	REAR BUMPER REFLECTOR N/S	SHIELD 225	\$165.00	X
2PCS	REAR BUMPER PDC SENSORS	CNE 68.00	\$510.00	1PC
1PC	REAR AIR VENT N/S	304 1200.00	\$120.00	/
1PC	REAR END PANEL	17	\$1,800.00	/
1PC	REAR END PANEL TOP GARNISH	318.00	\$392.00	X
1PC	REAR SPLASH SHIELD N/S	855.00	\$485.00	/
1PC	TAILLAMP N/S	202	\$1,050.00	/
			\$11,535.00	
	S.NETT			
1SET	REAR BUMPER CLIPS	NEC	\$80.00	50
1SET	REAR BUMPER TOP RETAINER CLIPS	NEC	\$80.00	30
1PC	REAR END PANEL SEALANT	NEC	\$60.00	50
	TO CHECK WIRING		\$50.00	20
	TO DISMANTLE & REPLACED REAR PDC SENSOR		\$80.00	50
	TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00	X
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00	80
	TO SPRAY RUST PROOFING		\$100.00	30
	TO TRANSFER TAILGATE MECHANISM		\$100.00	X
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$900.00	750
	TO PUTTY & SPRAY PAINTING		\$1,500.00	1000
	TOTAL		\$14,755.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-6338
W/C
5070.4
7132.40
5704.32