

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0970/2020/NS
DATE : 14-Dec-20
WIP : 62282

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : YN 8284 A

LONPAC INSURANCE BHD

100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Hi Adrian

**5 days exclude 1 Sunday - ok
jb 2 Feb 21**

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

OWNER'S NAME : MS MARY KWOK SIN FANG
ADDRESS : 3 PARRY TERRACE
SINGAPORE 547102
TELEPHONE : HP +65 92778807
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800116048-01
VEHICLE NO : **SJB 1982 E**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 27/9/2018
ENGINE NO : CHZ B16392
CHASSIS NO : WAUZZZ8V1JA153688
MILEAGE : 26897KM
DATE IN : 11-Dec-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Dec-20
PLACE OF ACCIDENT : TURNHOUSE RD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 1982 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES
1	TO REMOVE AND TRANSFER LHS FRONT AND REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. S/N	\$ 560.00
2	TO INSTALL SOLAR FILM FOR LHS REAR WINDOW GLASS. S/N	\$ 400.00
3	TO DISMANTLE AND RENEW LHS FRONT AND REAR DOOR. TO REPAIR LHS B-PILLAR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,450.00
4	TO RESPRAY LHS FRONT DOOR, LHS WING MIRROR COVER, LHS REAR DOOR AND LHS B-PILLAR.	\$ 3,300.00
5	TO CARRY OUT DIAGNOSTIC CHECK. S/N	\$ 192.00
TOTAL LABOUR CHARGES		: \$ <u>6,902.00</u>

***SURVEYOR'S
RECOMMENDATIONS***

\$ 560.00

\$ 1,400.00

\$ 1,550.00

\$ 192.00

\$ 3,702.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 1982 E

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
1	FRONT DOOR - LH		\$ 2,267.00	\$	2,267.00
2	FRONT DOOR OUTER SEAL - LH	NEC	\$ 159.00	\$	158.50
3	BONDING AGENT	NEC	\$ 47.00		
4	CLEANING SOLUTION	NEC	\$ 65.00		
5	FRONT DOOR ATTACHMENT PARTS		\$ 238.00		
6	FRONT DOOR CATCH		\$ 104.00		
7	EXTERIOR MIRROR MOUNTING - LH		\$ 1,013.00		
8	MIRROR CAP - LH		\$ 148.00		
9	WINDOW SLOT SEAL - LH FRONT		\$ 266.00		
10	B PILLAR TRIM - LH		\$ 103.00		
11	REAR DOOR - LH		\$ 2,267.00	\$	2,267.00
12	REAR DOOR OUTER SEAL - LH	NEC	\$ 159.00	\$	158.50
13	BONDING AGENT	NEC	\$ 47.00		
14	CLEANING SOLUTION	NEC	\$ 65.00		
15	REAR DOOR ATTACHMENT PARTS		\$ 127.00		
16	REAR DOOR CATCH		\$ 93.00		
17	WINDOW SLOT SEAL - LH REAR		\$ 266.00		
18	B PILLAR TRIM - LH		\$ 115.00		
19	WINDOW REGULATOR - LH		\$ 246.00		
20	CORNER TRIM - LH		\$ 73.00		
21	DOOR WINDOW - LH REAR		\$ 209.00		
22	SUNDRIES		\$ 300.00	\$	8.40
TOTAL SPARE PARTS		:	\$ 8,377.00	\$	4,859.40
TOTAL LABOUR CHARGES		:	\$ 6,902.00	\$	3,702.00
GRAND TOTAL		:	\$ 15,279.00	\$	8,561.40

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-14/01/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT