



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0847/2020/NS
DATE	:	4-Nov-20
WIP	:	56644

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : FBA 7945 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

OWNER'S NAME	:	MR PHUA CHENG MIEN(PAN ZHENGMIAN)
ADDRESS	:	BLK 31 JALAN RAMA RAMA #12-03 SINGAPORE 32911
TELEPHONE	:	HP +65 81388397
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	2070026602
VEHICLE NO	:	SMS 2762 S
MODEL CODE	:	AUDI Q3 SPORTSBACK 1.4 TFS
MODEL YEAR	:	19/2/2020
ENGINE NO	:	CZD 888513
CHASSIS NO	:	WAUZZZF38L1048800
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	4-Nov-20
PLACE OF ACCIDENT	:	2 GEYLANG LORONG 10



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 2762 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 400.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500 ✓
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,700.00	1250 ✓ Bumper 550 Spoiler 300 Wheel Arc x2 = 200 x 2 2400 1250
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,572.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 2762 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	REMARKS
S/NETT			
1 FRONT BUMPER <i>Del'd</i>		\$ 2,615.00	✓ 2091.60
2 FRONT BUMPER FIXING PARTS		\$ 410.00	+
3 FRONT BUMPER CLOSING ELEMENT - RH		\$ 58.00	+
4 FRONT BUMPER TRIM		\$ 352.00	+
5 FRONT BUMPER GRILLE - CENTRE		\$ 215.00	+
6 ULTRASOUND SENSOR SUPPORT - LH/RH	2	\$ 50.00	+
7 FRONT BUMPER CLOSING ELEMENT		\$ 188.00	+
8 FRONT SPOILER <i>Del'd</i>		\$ 754.00	✓ 603.20
9 FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 151.00	+
10 AIR GUIDE GRILLE TRIM - RH		\$ 162.00	+
11 AIR GUIDE GRILLE ULTRASOUND SENSOR SUPPORT - RH		\$ 25.00	+
12 RADIATOR GRILLE		\$ 1,907.00	+
13 RADIATOR GRILLE STRIKER PLATE		\$ 241.00	+
14 RADIATOR GRILLE INNER COVER		\$ 241.00	+
15 FRONT PARKING AID SENSOR		\$ 242.00	+
16 FRONT PARKING AID SEAL RING	4	\$ 14.00	+
17 FRONT BUMPER FOAM FILLER PIECE		\$ 101.00	+
18 FRONT BUMPER CARRIER		\$ 834.00	+
19 FRONT BUMPER GUIDE SECTION - RH		\$ 38.00	+
20 FRONT FENDER - RH		\$ 1,271.00	+
SUB TOTAL SPARE PARTS	:	\$ 9,869.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 2762 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS		\$ 62.00	X
22	FRONT FENDER BRACKET - RH		\$ 31.00	X
23	FRONT FENDER BRACE - RH		\$ 87.00	X
24	FRONT WHEEL HOUSING LINER - RH		\$ 237.00	X
25	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 100.00	X
26	LED HEADLIGHT - RH		\$ 5,526.00	X
27	LIFT CYLINDER - RH		\$ 208.00	X
28	FRONT WHEEL COVER - LH/RH	2	\$ 1,060.00	✓ 248.00
29	FRONT NO PLATE	S/N	\$ 60.00	X
30	SUNDRIES		\$ 300.00	X
TOTAL SPARE PARTS		:	\$ 17,540.00	
TOTAL LABOUR CHARGES		:	\$ 8,572.00	
GRAND TOTAL		:	\$ 26,112.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *11/12/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 03 Days ✓*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT