

## SCOPE OF WORK

- 1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

VEHICLE TYPE	DBL CAB	REGISTRATION NO	YN 4220 K	REPAIR TYPE	ACCIDENT
MAKE/MODEL	ISUZU	UNIT	CDA	CONTRACTOR	SMRT

S/N	ITEM DESCRIPTION	PARTS					LABOUR		
		PARTS QTY	PARTS COST PER UNIT (\$)	MARK UP RATE	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	MAN-HOUR RATE (\$)	MAN-HOUR QTY	TOTAL MAN-HOUR COST (\$)
SCOPE OF REPAIRS									
A	Labour								
1	Remove & replace front dented bumper						-		-
2	Remove & replace front dented bumper support						-		-
3	Remove & replace L/H fog lamp						-		-
4	Remove & replace front dented number plate						-		-
5	Remove & replace front passenger dented door shell						-		-
6	Transfer front passenger door inner panel, door handle & accessories to new door shell						-		-
7	Replace passenger door signal lamp						-		-
8	Remove & replace passenger door step casing						-		-
9	Remove & replace front L/H signal lamp						-		-
10	Remove & replace L/H head lamp						-		-
11	Remove & replace radiator grill						-		-
12	Replace L/H corner panel						-		-
13	Remove & replace L/H rear view mirror						-		-
14	Remove & replace wind screen						-		-
15	Replace wind screen moulding						-		-
16	Water seepage for wind screen						-		-
17	Panel beat & align dented passenger door panel						-		-
18	Align rear L/H dented door						-		-
19	Align dented driver door						-		-
20	Align tilted cabin						-		-
21	Remove & replace front panel sticker						-		-
22	Putty & spray whole complete front cabin						-		-
23	Wiring for all replacement lighting						-		-
	Remark : Pls note that above quote is based on visual assessment only. Any other repairs / parts required during the repair process will be forwarded with supplementary quote according.								