

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 18 Jan 2021

## **Preliminary Advice**

Insured Vehicle No : SJD5029X  
TP Vehicle No : SMV1241U Accident Date : 12/12/2020  
Make : HONDA CITY Assignment Date : 18/01/2021  
Date of Inspection : 15/12/2020 Est. Duration of Repair : 4  
Inspection At : ADVANCE AUTO GARAGE  
10 KAKI BUKIT ROAD 2, #01-21 FIRST EAST CENTRE  
SINGAPORE 417868

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,915.10
Revised Amount	:S\$	6,496.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,496.60
Lump Sum Repair	:S\$	5,200.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : survey on wp