

SOMPO

Vehicle number	SLJ436G
Make / Model	TOYOTA/COROLLA
Chassis number	MR053REH104556708
Accident date	5/12/20
Reference	2012-08

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	BOOTLID	822.50 X
1	BOOTLID EMBLEM LOGO	69.00 X
1	BOOTLID EMBLEM -COROLLA	46.00 X
1	BOOTLID EMBLEM - ALTIS	50.60 X
1	BOOTLID CHROME GARNISH	265.65 X
1	BOOTLID LICENCE PLATE LAMP	72.40 X
2	BOOTLID LAMP	763.36 X
2	BOOTLID LAMP INNER SEAL	64.40 X
1	BOOTLID LOCK	437.00 X
1	BOOTLID LOCK CATCH	23.00 X
1	BOOTLID INNER TRIM	396.75 X
1	BOOTLID WEATHERSTRIP	281.30 X
1	END PANEL	672.75 X
1	END PANEL TOP GARNISH	241.50 X
1	REAR BUMPER	557.75 <i>de</i>
2	REAR BUMPER RETAINER	130.00 <i>LH-104 RH X</i>
2	REAR BUMPER REFLECTOR	181.20 X
2	REAR BUMPER BRACKET	149.50 <i>LH-? RH X</i>
1	REAR BUMPER REINFORCEMENT	453.20 <i>X 7</i>
4	PDC SENSOR	722.20 <i>200? plus</i>
1	SENSOR WIRE HARNESS	381.00 X
		6781.06
	Less 25 %	1695.26
	Subtotal	5085.80
	Balance C/F	5085.80
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	REAR BUMPER CLIP	40.00 <i>30 net</i>
1 SET	REAR FENDER INNER TRIM CLIP	30.00 X
1 SET	REAR NUMBER PLATE	70.00 X
1 SET	END PANEL GARNISH CLIP	30.00 X
1 SET	BOOTLID INNER TRIM CLIP	30.00 X
1	JOINT SEALANT	100.00 X
	Subtotal	300.00
	Balance C/F	5385.80

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHEECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE, REFIT REAR LINING , TRIM AND GARNISH	200.00 X
3	REMOVE, RENEW REAR REVERSE SENSOR	120.00 30
4	REMOVE AND RENEW REAR EXHAUST	120.00 X
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 X
6	PANEL BEATING ON AFFECTED AREAS	1200.00 200
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00 200
8	APPLY ANTI RUST ON AFFECTED AREAS	100.00 X
Subtotal		3200.00
Grand total		8585.80

Taufik 97445449
 -WP- 14/12/200 545pm
 L/S Resurvey after repair
 2 days
 for fah & hantawon.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: