



Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax : +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMHCSNA00004132000	Date of Loss:	12/11/2020
Vehicle Reg. No.:	SME8937P	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HAMSTER CAR RENTAL PTE LTD		
Driver:	CHUA CHONG LOONG		
Make/Model:	VOLKSWAGEN GOLF, 1.4 TSI HL (A)	Vehicle Reg. Date:	22/10/2018
Vehicle Colour:	SILVER		
Engine No:	CHZC16639	Chassis No:	WVWZZZAUZJW303627
Odometer:	40537 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Remarks:	KINDLY CONTACT OUR MOTOR CLAIMS OFFICER MS. KON (9739 6433) FOR SURVEY.		
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)		

COST OF CLAIMS	Amount
Parts	50,262.00
Miscellaneous Items	312.00
Labour	2,669.04
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	53,243.04
+ GST 7.00% (S\$)	3,727.01
Nett Amount (S\$)	56,970.05

This claim is handled by: **KON YIN SIEW**

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Dec 2020)

Parts: 144 VOLKSWAGEN GOLF 1.4 TSI HL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **Goldbell Engineering Pte Ltd/SME8937P/14/12/2020 16:33**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Total Parts	0.00	0.00	27107 *50,262.00 F
Total Parts (\$)						50,262.00

F=Franchise part.

Goldbell Engineering Pte Ltd/SME8937P/14/12/2020 16:33. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Total Of Extras	230 312.00
			Sub Total (\$\$) 312.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total of Labour	New	1,986.60
2	Total Paint Including Material	New	682.44
			Gross Labour Cost (\$\$) 2,669.04

Goldbell Engineering Pte Ltd/SME8937P/14/12/2020 16:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

