



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

ESTIMATE

NO : QUOT202012-000053(00)

DATE : 14/12/2020

POLICY NO : 999995580

VEH REG NO : SLE1036Y

MAKE/MODEL : MERCEDES BENZ GLC250
4MATIC (R18 LED)

CHASSIS NO : WDC2539462F058518

ENGINE NO : 27492030499549

REG. DATE : 2016

YOUR REF NO : SLV8727B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 06/12/2020

TP VEH REG NO : SLV8727B

*Not Authorised
Repairing B4 repair*

4 days

16/12/2020

Estimate Repair Cost to Vehicle No : SLE1036Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Front door - LH	1	2,696.00	2,696.00
2 Front door weatherstrip - LH	1	328.00	328.00
3 Front door trimboard rivets - LH	20	60 (SN) 13.00	260.00
4 Rear door - LH	1	2,925.00	2,925.00
5 Rear door weatherstrip - LH	1	328.00	328.00
6 Rear door trimboard rivet - LH	20	60 (SN) 13.00	260.00
			6,797.00
		Less 10%	679.70
			6,117.30
LABOUR			
7 To transfer LH front and rear damaged door interior mechanism and glass to new door	1	300.00	300.00
8 To panel beat and straighten LH front & rear door hinges, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00
9 To check and rectify wiring system	1	80.00	80.00
10 To putty and spray paint on affected areas	1	800.00	800.00
11 To apply rust-proofing on replaced and repaired panels	1	120.00	120.00
			2,100.00

TOTAL S\$ 8,217.30

ADD GST @ 7% 575.21

GRAND TOTAL S\$ 8,792.51

SINGAPORE DOLLAR EIGHT THOUSAND SEVEN HUNDRED NINETY-TWO AND CENTS FIFTY-ONE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE