

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXXX580H
RAJAKUMAR CHOPPA MAHARAJAN
BLK 71 BEDOK SOUTH ROAD
#16-256
SINGAPORE 460071
TEL : FAX :
PH : 98512815
ATTN :

ESTIMATE BILL

Number : EB00005590
Date : 15/12/2020
Case No : AD00011487
Vehicle No : SGJ1214H
Chassis: MR053HY4204192606
Year of Mfr 2006
Policy No 5119494348
Model : TOYOTA VIOS 1.5E A

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT FENDER LH	1.0	179.90	25	134.93
2	FRONT BUMPER	1.0	278.90	25	209.18
3	FRONT BUMPER RETAINER LH	1.0	20.80	25	15.60
4	HEADLAMP LH	1.0	249.96	25	187.47
5	FRONT FENDER INNER SHIELD LH	1.0	67.85	25	50.89
6	FRONT FENDER SIGNAL LAMP LH	1.0	78.95	25	59.21
7	ENGINE MOUNTING SET	1.0	486.90	25	365.18
	List Price - Parts Sub Total				1,022.46
8	FRONT WHEEL RIM LH	1.0	680.00	0	680.00
9	FRONT TYRE LH	1.0	380.00	0	380.00
	Special Nett Price - Parts Sub Total				1,060.00
	Parts Total				2,082.46
10	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
11	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
12	ANTI-RUST COATING	1.0	150.00	0	150.00
13	WIRING	1.0	40.00	0	40.00
14	TWO WHEEL ALIGNMENT	1.0	80.00	0	80.00
	Labour 1 Sub Total				1,670.00
SINGAPORE DOLLARS : FOUR THOUSAND FIFTEEN AND CENTS THIRTEEN ONLY			Less Excess		0.00
			SUBTOTAL		3,752.46
			GST 7.00%		262.67
			TOTAL		4,015.13

Date of accident : 11/12/2020 08:15 PM. Place : BUKIT PANJANG RING ROAD X JUNCTION

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE