

HOCK WAH MOTOR WORKSHOP PTE LTD

aka Cecilia

INDUSTRIAL PARK E
 H AVE 4,
 2 SINGAPORE 489977
 655 FAX : 6441 5355/6243 8121
 200104141D GST Reg. No. 20-0104141-D

R/P \$900

SXXXX580H
 JAKUMAR CHOPPA MAHARAJAN
 BLK 71 BEDOK SOUTH ROAD
 #16-256
 SINGAPORE 460071
 TEL : FAX :
 PH : 98512815
 ATTN :

*Not Authorized
 below
 3/1/21
 [Signature]
 3 days.*

ESTIMATE BILL

Number : EB00005590
 Date : 15/12/2020
 Case No : AD00011487
 Vehicle No : SGJ1214H
 Chassis : MR053HY4204192606
 Year of Mfr : 2006
 Policy No : 5119494348
 Model : TOYOTA VIOS 1.5E A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT FENDER LH <i>N</i>	1.0	179.90	25	134.93
2	FRONT BUMPER <i>N</i>	1.0	278.90	25	209.18
3	FRONT BUMPER RETAINER LH <i>N</i>	1.0	20.80	25	15.60
4	HEADLAMP LH <i>N X</i>	1.0	249.96	25	187.47
5	FRONT FENDER INNER SHIELD LH <i>N X</i>	1.0	67.85	25	50.89
6	FRONT FENDER SIGNAL LAMP LH <i>N X</i>	1.0	78.95	25	59.21
7	ENGINE MOUNTING SET <i>N X</i>	1.0	486.90	25	365.18
List Price - Parts Sub Total					1,022.46
8	FRONT WHEEL RIM LH <i>cut/n/cx</i>	1.0	680.00	0	680.00
9	FRONT TYRE LH <i>N X</i>	1.0	380.00	0	380.00
Special Nett Price - Parts Sub Total					1,060.00
Parts Total					2,082.46
10	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
11	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
12	ANTI-RUST COATING	1.0	150.00	0	150.00
13	WIRING	1.0	40.00	0	40.00
14	TWO WHEEL ALIGNMENT	1.0	80.00	0	80.00
Labour 1 Sub Total					1,670.00
<div style="border: 1px solid blue; padding: 5px;"> <p>Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>					
SINGAPORE DOLLARS : FOUR THOUSAND FIFTEEN AND CENTS THIRTEEN ONLY			Less Excess		0.00
			SUBTOTAL		3,752.46
			GST 7.00%		262.67
			TOTAL		4,015.13

*#
X
X
X
X
X
X
300
550
30
20
X*

Date of accident : 11/12/2020 08:15 PM. Place : BUKIT PANJANG RING ROAD X JUNCTION

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE