

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance
Date: 15/12/2020
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLF2976Y
CHASSIS NO: NSP1707017543
MAKE / MODEL: Toyota Sienta 1.5 x Auto
DATE OF ACCIDENT: 15/12/2020
YOUR INSURED VEHICLE NUMBER: GBK3730A
MILEAGE: 307862 km

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE	
1	F/L door / DD	1PC	\$ 1,404.00	\$ 1,404.00	1,233.90
2	F/L door regulator 2 / OT	1PC	\$ 480.50	\$ 480.50	380
3	F/L door window motor 2 / Sum	1PC	\$ 528.30	\$ 528.30	420
4	R/L door / DD	1PC	\$ 1,404.00	\$ 1,404.00	1,279
5	R/L fender / DD	1PC	\$ 1,255.00	\$ 1,255.00	980
6	R/L fender rubber pad / SCR	1PC	\$ 280.00	\$ 280.00	150
7	R/L door rubber pad / SCH	1PC	\$ 390.00	\$ 390.00	280
8	Rear bumper / CKY	1PC	\$ 1,257.83	\$ 1,257.83	788.70
LIST TOTAL S\$:				\$ 6,999.63	5,511.60
25.00% DISCOUNT S\$:				\$ 1,749.91	-25%
				\$ 5,249.72	4,133.70
LH Side mirror cover / CKY					
LH Side mirror cover / CKY					
SPECIAL NETT					
1	Bumper clips / NEC	1 SET	\$	80.00	90
2	Body sealant / NEC	1PC	\$	300.00	80
Special Nett Total S\$:				\$ 380.00	90

LABOUR CHARGES

1	To labour charge for removing F/L door, R/L door, rear bumper out to facilitate replacement of parts. Also repair R/L fender	\$ 1,200.00	/
2	To respray rear bumper, F/L door, R/L door and R/L fender	\$ 1,200.00	1000
3	To remove and install rear tailgate glass	\$ 120.00	X
4	Transfer tailgate mechanism	\$ 100.00	X
5	To configure keyless network security system back to factory specification	\$ 300.00	X
6	To deactivate and activate high voltage hybrid battery as a requirement for safety precautions	\$ 300.00	X
LABOUR TOTAL S\$:		\$ 3,220.00	2300 + 50.
TOTAL S\$:		\$ 8,849.72	
7% GST		\$ 619.48	
GRAND TOTAL S\$:		\$ 9,469.20	

Tuning Fee \$50

Repair dy - 6 days

See LIS
After priming

See Pm Lkm

16/12/2020

TP with priming

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 15/12/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE
PARTS SUPPLEMENTARY

VEHICLE NO. SLF2976Y

CHASSIS NO : NSP1707017543

MAKE / MODEL : Toyota Sienta Hybrid 1.5G Auto

DATE OF ACCIDENT : 15/12/2020

YOUR INSURED VEHICLE NUMBER :GBK3730A

MILEAGE : 307862km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	LH door bottom hinge 1x <i>5pc</i>	1PC	\$120.00	\$120.00 x
2	LH door upper hinge 1x <i>5pc</i>	1PC	\$180.00	\$180.00 x
3	LH side mirror cover <i>/CRA</i>	1PC	\$180.00	\$180.00 x
4	LH side mirror assy <i>/CRA</i>	1PC	\$980.00	\$980.00 x
LIST TOTAL S\$:				\$1,460.00
25.00% DISCOUNT S\$:				\$365.00
				\$1,095.00

4,133.70
870
90
2,300

7,443.70
- 20%

5,954.96

45
\$5,950
6 days

1,160
- 25%

870

1,460
- 365

1,095

Parts - 5249.72 + 1095 = \$6344.72

S/N = \$90

labor = \$2300

Total = \$8734.72 - 20% = \$6987.78

LI = \$7000