

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0984/2020/NS
DATE : 16-Dec-20
WIP : 63147

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMJ 2140 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TAN BOON ANN
ADDRESS : 9A KING'S ROAD
SINGAPORE 268059
TELEPHONE : HP +65 96648580
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5102615748-02
VEHICLE NO : **SKR 9428 R**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 18/3/2015
ENGINE NO : CZC 230387
CHASSIS NO : WAUZZZ8V7F1088403
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Dec-20
PLACE OF ACCIDENT : BUGIS JUNCTION CARPARK EXIT GANTRY

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKR 9428 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00 ✓	✓
2	TO DISMANTLE AND RENEW RHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 500 ✓	✓
3	TO RESPRAY RHS REAR DOOR.	\$ 900.00 550 ✓	✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 2,422.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 9428 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR DOOR - RH <i>Dented</i>		\$ 2,494.00 ✓	1,995.20
2 REAR DOOR OUTER SEAL - RH <i>Neu</i>	NEC	\$ 159.00 ✓	127.20
3 BONDING AGENT <i>} Neu</i>	NEC	\$ 47.00 +	
4 CLEANING SOLUTION <i>} Neu</i>	NEC	\$ 65.00 +	
5 REAR DOOR ATTACHMENT PARTS <i>Neu</i>		\$ 127.00 +	
6 REAR DOOR CATCH <i>?</i>		\$ 93.00 ?	
7 SUNDRIES <i>?</i>		\$ 200.00 ?	5.76
TOTAL SPARE PARTS	:	\$ 3,185.00	
TOTAL LABOUR CHARGES	:	\$ 2,422.00	
GRAND TOTAL	:	\$ 5,607.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lin
SURVEYED DATE : 18/12/20.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT