

ESTIMATE*

NO SHC3588X

DATE 11/08/20 12:00 AM

: HYUNDAI IONIQ G3

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$418.30 Rx
1	FRONT BUMPER BRACKET RH			\$35.00 X u n
1	FRONT BUMPER REINFORCEMENT			\$1,075.10 X u n
1	FRONT BUMPER CENTRE MOULDING			\$368.50 ent
1	FRONT RADIATOR GRILLE			\$1,409.10 ent
1	FRONT BUMPER LOWER STIFFNER			\$285.10 X u n
1	HEAD LAMP SUPPORT PANEL			\$949.30 X u n
1	HEAD LAMP RH			\$1,993.65 ent
1	FRONT DAY LIGHT RH			\$642.50 X u n
1	BUMPER GRILLE RH			\$186.90 ent X u n
	SUB TOTAL		3771.25	\$7,363.45
	LESS 20%			\$1,472.69
	DISCOUNTED TOTAL		3017.	\$5,890.76
1	FRONT NUMBER PLATE W/HOLDER		55	\$55.00 One
				\$55.00
	Labour Charge			
	Panel Beating		320	\$640.00
	Spray Painting Charge		300	\$500.00
	WIRING	650	30	\$60.00
	Tuff Kote		u n X	\$60.00
	TOTAL LABOUR			\$1,260.00
	ESTIMATE TOTAL		43722 2 days #	\$7,205.76

Tanphir 97495749
 - w/ 16/12/2025
 62 days

p/p Resurvey new parts
 Resurvey after repair
 Tanphir E Khambum

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: