

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMG9915K
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES2091013/YISHUN

Date: 16 Dec 2020

Policy No: 5115339346

Veh Reg No: SMG9915K

Make/Model: MITSUBISHI MIT.
ATTRAGE 1.2 CVT

Chassis No: MMBSTA13AKH000651

Engine No: 3A92UHL9375

Reg. Date: 08/01/2019

WS Ref: TP/MSIG

Claim Type: Third Party

Accident Date: 15/12/2020

TP Veh Reg No: SLH1903D

Not Authorized

Recovery B4 point

9 days

Estimate Repair Cost to Vehicle No :SMG9915K

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Net Price				
1 REAR BUMPER	748.00	1 PC	748.00	✓
2 REAR BUMPER RH SIDE RETAINER	29.00	1 PC	29.00	✓
3 REAR BUMPER RH SIDE MUD GUARD	49.00	1 PC	49.00	?
4 REAR BUMPER CLIPS	4.00	5 PCS	20.00	✓
5 BOOTLID	791.00	1 PC	791.00	✓
6 REAR BOOTLID INNER LOCK	206.00	1 PC	206.00	✓
7 REAR BOOTLID INNER RUBBER	157.00	1 PC	157.00	✓
8 REAR BOOTLID LOGO	45.00	1 PC	45.00	69N ✓
9 REAR BOOTLID EMBLEM (ATTRAGE)	45.00	1 PC	45.00	11N ✓
10 TAILLAMPS	335.00	2 PCS	670.00	✓
11 RH PANEL	67.00	1 PC	67.00	?
12 RH PANEL CLIP	6.00	1 PC	6.00	✓
13 REAR END PANEL	425.00	1 PC	425.00	R
14 REAR END PANEL INNER TOP GARNISH	72.00	1 PC	72.00	69N ✓
15 REAR END PANEL INNER TOP GARNISH CLIPS	5.00	2 PCS	10.00	✓
16 REAR SPARE TYRE PANEL TOP BOARD	195.00	1 PC	195.00	✓
17 REAR RH FENDER	755.00	1 PC	755.00	R
			4,290.00	
	Less 10%		429.00	3,861.00
Special Net				
18 REAR BUMPER LOWER SKIRT	480.00	1 PC	480.00	✓
19 REVERSE SENSORS	200.00	1 SET	200.00	✓
20 REAR BOOTLID EMBLEM (MIVEC)	35.00	1 PC	35.00	✓
21 REAR END PANEL SEALANT	40.00	1 PC	40.00	305N ✓
22 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
			795.00	795.00

C & C logo

#40 9N

List Price \$980

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG

Claim Type: Third Party

Accident Date: 15/12/2020

TP Veh Reg No: SLH1903D

Estimate No: ES2091013/YISHUN

Date: 16 Dec 2020

Policy No: 5115339346

Veh Reg No: SMG9915K

Make/Model: MITSUBISHI MIT.
ATTRAGE 1.2 CVT

Chassis No: MMBSTA13AKH000651

Engine No: 3A92UHL9375

Reg. Date: 08/01/2019

Estimate Repair Cost to Vehicle No :SMG9915K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
23 TOWING	50.00	1 LA	50.00	✓
24 REMOVE & REFIX REAR BUMPER, LOWER SKIRT & ATTACHMENT, BOOTLID, SPOILER & ATTACHMENTS, TAILLAMPS, CUT, WELD & RENEW REAR END PANEL, RH TAILLAMP PANEL, REAR RH FENDER, KNOCK & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME	1,300.00	1 LA	1,300.00	1100 ✓ 980 ✓
25 PUTTY & RESPRAY REAR BUMPER, LOWER SKIRT, BOOTLID & SPOILER, REAR FENDERS, REAR END PANEL, REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	1,300.00	1 LA	1,300.00	1000 ✓
26 REMOVE & REFIX REVERSE CAMERA, RESET & POSITION	50.00	1 LA	50.00	✓ ✓
27 RUSTPROOFING	90.00	1 LA	90.00	✓ 60
28 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓ X
29 REMOVE & REFIX SEAT, CARPET, TOP ROOF LINING, GARNISH, ETC	120.00	1 LA	120.00	100 ✓
			3,010.00	3,010.00

Total S\$ 7,666.00

Add GST @ 7% 536.62

Total Amount Payable S\$ 8,202.62

Parts 3958 N
 Less 10% 395.80
 3562.20
 305 SN
 240
 6107.20

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE