

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	NCE BHD	Ref:	CS/LPC20014074/Kqd3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	16/06/2021	
			Code:	LPC2	
1.	Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLW 2745H	
	Policy No.	Z20VP05025865	Coverage (\$)	0.00	
	Claim No.	20/20/20/VP05/024018	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	18/12/2020	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA JAZZ (A)	c.c	1498	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	JHMGK5850JX203974	Colour	METALLIC DARK BLUE	
	Odometer	30880 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/55 R16	YOKOHAMA	8 mm	
	L/H Front Tyre	185/55 R16	YOKOHAMA	8 mm	
	R/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm	
	L/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/12/2020	Inspection Date	18/12/2020	
	Survey held at FALCON-AIR AUTO SERVICES PTE LTD (HQ)				
		176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721			
5a.	Remarks				
	A)THE MARKET VALUE IS S\$59,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				