



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH
Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62962706

Estimate : ES012095

Date : 17/12/2020
Vehicle Num. : SLW 2745H
Make/Model : HONDA JAZZ CVT-2017/2018
Chassis/Eng# : JHMGK5850JX203974
Accident Date : 16/12/2020
Claim No. :
Reference : O/D
Policy No. : Z20VP05025865

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED :				
1.	1 PC	BONNET		380.00
2.	2 PCS	BONNET HINGE	22.00	44.00
3.	1 PC	BONNET INSULATOR		65.00
4.	2 PCS	BONNET RUBBER (OUTER)	15.00	30.00
5.	2 PCS	BONNET RUBBER (INNER)	15.00	30.00
6.	1 PC	BONNET LOCK		65.00
7.	1 PC	RH FRONT FENDER		130.00
8.	1 PC	RH FRONT FENDER SHIELD		60.00
9.	2 PCS	HEADLAMP	1,000.00	2,000.00
10.	2 PCS	HEADLAMP RETAINER	32.00	64.00
11.	1 PC	RADIATOR GRILLE BASE		185.00
12.	1 PC	RADIATOR GRILLE LOGO		16.00
13.	1 PC	RADIATOR GRILLE LOGO BASE		18.00
14.	1 PC	RADIATOR GRILLE TOP COVER		15.00
15.	2 PCS	RADIATOR GRILLE CHROME MOULDING	15.00	30.00
16.	1 PC	FRONT BUMPER		340.00
17.	2 PCS	FRONT BUMPER SIDE RETAINER	6.00	12.00
18.	1 PC	FRONT NUMBER PLATE GARNISH		35.00
19.	1 PC	RADIATOR GRILLE CHROME GARNISH		100.00
20.	1 PC	FRONT BUMPER TOW COVER		11.00
21.	1 PC	FRONT BUMPER LOWER GRILLE		150.00
22.	1 PC	FRONT BUMPER LOWER SPOILER		240.00

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON INSURANCE PHD

300 BEACH ROAD #17-04/07

THE CONCOURSE 199555

ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Estimate : ES012095

Date : 17/12/2020

Vehicle Num. : SLW 2745H

Make/Model : HONDA JAZZ CVT-2017/2018

Chassis/Eng# : JHMGK5850JX203974

Accident Date : 16/12/2020

Claim No. :

Reference : O/D

Policy No. : Z20VP05025865

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	FRONT BUMPER REINFORCEMENT		190.00
24.	1 PC	FRONT SUPPORT PANEL		260.00
25.	2 PCS	AIR GUIDE	12.00	24.00
26.	1 PC	AIR CON CONDENSER		280.00
27.	1 PC	AIR CON LIQUID PIPE		95.00
28.	1 PC	AIR CON DISCHARGE HOSE		110.00
29.	1 PC	AIR CON SUCTION HOSE		110.00
30.	1 PC	AIR CON FAN COWLING		65.00
31.	1 PC	AIR CON FAN BLADE		35.00
32.	1 PC	AIR CON FAN MOTOR		180.00
33.	1 PC	RADIATOR		780.00
34.	1 PC	RADIATOR FAN COWLING		50.00
35.	1 PC	RADIATOR FAN BLADE		35.00
36.	1 PC	RADIATOR FAN MOTOR		160.00
37.	1 PC	COOLANT SPARE TANK		20.00
38.	1 PC	AIR DUCT		35.00
39.	1 PC	WIPER WASHER TANK		90.00
40.	1 PC	WIPER WASHER TANK NECK		12.00
41.	1 PC	FRONT BUMPER CENTER GARNISH		25.00
42.	2 PCS	FRONT FOG LAMP GARNISH	22.00	44.00
43.	2 PCS	FRONT FOG LAMP GARNISH CHROME	50.00	100.00
Total Parts Purchased S\$:				6,720.00
15.00% Of The Above Parts S\$:				1,008.00
Based On Cost Plus S\$:				7,728.00

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH
Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62962706

Estimate : ES012095

Date : 17/12/2020
Vehicle Num. : SLW 2745H
Make/Model : HONDA JAZZ CVT-2017/2018
Chassis/Eng# : JHMGK5850JX203974
Accident Date : 16/12/2020
Claim No. :
Reference : O/D
Policy No. : Z20VP05025865

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	10 PCS	SPECIAL NETT ITEMS : BONNET INSULATOR CLIP	4.00	40.00
2.	8 PCS	RH FRONT FENDER SHIELD CLIP	5.00	40.00
3.	10 PCS	FRONT BUMPER CLIP	4.00	40.00
4.	1 PC	FRONT NUMBER PLATE		45.00
5.	1 BOTTLE	COOLANT		40.00
Special Nett Total S\$:				205.00
LABOUR :				
TO FOCUS HEADLAMP				50.00
TO REMOVE/REFIX AIR CON CONDENSER, PIPE VACUUM AND TOP UP AIR CON GAS				120.00
TO STRAIGHTEN LH/RH FRONT CHASSIS, LH FRONT FENDER, RH FRONT DOOR, CUT/REWELD FRONT SUPPORT PANEL AND REPLACEMENT OF PARTS				1,000.00
TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT SUPPORT PANEL, LH/RH FRONT CHASSIS, LH/RH FRONT FENDER, RH FRONT DOOR				1,680.00
Labour Total S\$:				2,850.00
E. & O.E.			Total S\$:	10,783.00

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.