



Co. Reg. No. 199501140D
GST Reg. No. 199501140D

Not Notarized
Recovery B4 prison
EX ?

6 days

Unit Price	Amount S\$
------------	------------

QTY	DESCRIPTION	UNIT	PRICE	TOTAL	REMARKS
1	1 PC				
2	2 PCS				
3	1 PC				
4	2 PCS				
5	2 PCS				
6	1 PC				
7	1 PC				
8	1 PC				
9	2 PCS				
10	2 PCS				
11	1 PC				
12	1 PC				
13	1 PC				
14	1 PC				
15	2 PCS				
16	1 PC				
17	2 PCS				
18	1 PC				
19	1 PC				
20	2 PCS				
21	1 PC				
22	1 PC				
23	1 PC				
24	1 PC				
25	1 PC				
26	1 PC				
27	1 PC				
28	1 PC				
29	1 PC				
30	1 PC				
31	1 PC				
32	1 PC				
33	1 PC				
34	1 PC				
35	1 PC				
36	1 PC				
37	1 PC				
38	1 PC				
39	1 PC				
40	1 PC				
41	1 PC				
42	1 PC				
43	1 PC				
44	1 PC				
45	1 PC				
46	1 PC				
47	1 PC				
48	1 PC				
49	1 PC				
50	1 PC				
51	1 PC				
52	1 PC				
53	1 PC				
54	1 PC				
55	1 PC				
56	1 PC				
57	1 PC				
58	1 PC				
59	1 PC				
60	1 PC				
61	1 PC				
62	1 PC				
63	1 PC				
64	1 PC				
65	1 PC				
66	1 PC				
67	1 PC				
68	1 PC				
69	1 PC				
70	1 PC				
71	1 PC				
72	1 PC				
73	1 PC				
74	1 PC				
75	1 PC				
76	1 PC				
77	1 PC				
78	1 PC				
79	1 PC				
80	1 PC				
81	1 PC				
82	1 PC				
83	1 PC				
84	1 PC				
85	1 PC				
86	1 PC				
87	1 PC				
88	1 PC				
89	1 PC				
90	1 PC				
91	1 PC				
92	1 PC				
93	1 PC				
94	1 PC				

1pc / front grille stay — 10.00

CONTINUE /

Parts - 6293.95

Supply - 11 50

S/N - 155.00

Labov - 1820.00

total - 98280.45 ✓ o/c

912

FALCON AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : 1 Blok 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575221) Tel: 6452-0880, 6458-0880 Fax: 6454-2862
Tempines 193 : 93 Blok 906C #01-20G S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 6 Pandan Loop (Blok 1/Blok K) S(128226) Tel: 6779-5665 Fax: 6779-1111



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DFALCON INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention: Motor Claim Department

Contact: 62507388 Fax No.: 62962706

Estimate: ES012095

Date: 17/12/2020

Vehicle Num: SLV 2745H

Make/Model: HONDA JAZZ CVT-2017/2018

Chassis/Eng#: JHMGK5850JX203974

Accident Date: 16/12/2020

Claim No.:

Reference: O/D

Policy No.: Z20VP05025865

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	FRONT BUMPER REINFORCEMENT	190.00	190.00
24.	1 PC	FRONT SUPPORT PANEL	260.00	260.00
25.	2 PCS	AIR GUIDE	12.00	24.00
26.	1 PC	AIR CON CONDENSER	280.00	280.00
27.	1 PC	AIR CON LIQUID PIPE	95.00	95.00
28.	1 PC	AIR CON DISCHARGE HOSE	110.00	110.00
29.	1 PC	AIR CON SUCTION HOSE	110.00	110.00
30.	1 PC	AIR CON FAN COWLING	65.00	65.00
31.	1 PC	AIR CON FAN BLADE	35.00	35.00
32.	1 PC	AIR CON FAN MOTOR	180.00	180.00
33.	1 PC	RADIATOR	780.00	780.00
34.	1 PC	RADIATOR FAN COWLING	50.00	50.00
35.	1 PC	RADIATOR FAN BLADE	35.00	35.00
36.	1 PC	RADIATOR FAN MOTOR	160.00	160.00
37.	1 PC	COOLANT SPARE TANK	20.00	20.00
38.	1 PC	AIR DUCT	35.00	35.00
39.	1 PC	WIPER WASHER TANK	20.00	20.00
40.	1 PC	WIPER WASHER TANK NECK	12.00	12.00
41.	1 PC	FRONT BUMPER CENTER GARNISH	25.00	25.00
42.	2 PCS	FRONT FOG LAMP GARNISH	24.00	48.00
43.	2 PCS	FRONT FOG LAMP GARNISH CHROME	100.00	200.00
Total Parts Purchased S\$:			5473	6720.00
15.00% Of The Above Parts S\$:			820.95	1008.00
Based On Cost Plus S\$:			6293.95	7728.00

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07, 13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches: Tampines S(193) Blk 906/6 #01-201/516/7RA40 Tel: 6789-7997 Fax: 6789-7997 No 8 Pandan Loko (Blk 1-Blk K1) S(128226) Tel: 6779-5665 Fax: 6779-1110



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH
Attention: Motor Claim Department
Contact: 62507388 Fax No.: 62962706

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

Estimate: ES012095

Date: 17/12/2020
Vehicle Num: SLW 2745H
Make/Model: HONDA JAZZ CVT-2017/2018
Chassis/Eng#: JHMGK5850JX203974
Accident Date: 16/12/2020
Claim No.:
Reference: O/D
Policy No: Z20VP05025865

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	10 PCS	SPECIAL NETT ITEMS		
2.	8 PCS	BONNET INSULATOR CLIP	4.00	40.00
3.	10 PCS	RH FRONT FENDER SHIELD CLIP	5.00	50.00
4.	1 PC	FRONT BUMPER CLIP	4.00	40.00
5.	1 BOTTLE	FRONT NUMBER PLATE		45.00
		COOLANT		40.00
		Special Nett Total S\$:		205.00
		LABOUR:		
		TO FOCUS HEADLAMP		50.00
		TO REMOVE/REFIX AIR CON CONDENSER, PIPE		120.00
		VACUUM AND TOP UP AIR CON GAS		1.000.00
		TO STRAIGHTEN LH/RH FRONT CHASSIS, LH FRONT FENDER, RH		
		FRONT DOOR, CUT/REWELD FRONT SUPPORT PANEL AND		
		REPLACEMENT OF PARTS		1.000.00
		TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT BUMPER		
		REINFORCEMENT, FRONT SUPPORT PANEL, LH/RH FRONT		
		CHASSIS, LH/RH FRONT FENDER, RH FRONT DOOR		1.680.00
		Labour Total S\$:		2.850.00

E & O.E.

Total S\$ 10,783.00

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7867
Branches: Tampines: 93 Blk 909A #01-790/5-528840 Tel: 6789-7997 Fax: 6789-7997 • Jurong East: 100 Raffles Place #01-17/18/19 S(128226) Tel: 6779-5665 Fax: 6779-1110



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

PAC INSURANCE BHD
3 BEACH ROAD #17-04/07
CONCOURSE 199555
ATTENTION: GERALD POH
Location: Motor Claim Department
Tel: 62507388 Fax No.: 62962706

Supplementary Estimate : ES012129

Date: 17/02/2021
Vehicle Num.: SLW 2745H
Make/Model: HONDA JAZZ CVT-2017/2018
Chassis/Eng#: JHMGK5850JX203974
Accident Date: 16/12/2020
Claim No.:
Reference: O/D
Policy No.: Z20VP05025865

Quantity	Particular	Unit Price	Amount S\$
----------	------------	------------	------------

1 PC	PARTS PURCHASED : FRONT GRILLE STAY		10.00
	Total Parts Purchased S\$:		10.00
	15.00% Of The Above Parts S\$:		1.50
	Based On Cost Plus S\$:		11.50

E. & O.E.

Total S\$:

11.50

FALCON AIR AUTO SERVICES PTE LTD

Estimate was prepared from visual inspection. Further materials and labour charges may be required when repair is completed. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg