ESTIMATED ACCIDENT REPAIR COST



CCIDENT TIME 21:26HRS			7	BUS REGISTRATION NUMBER	SMB3054K		
REPORTED	40.00		7		SD		
ACCIDENT DATE	10-D	ec-20 		BUS TYPE (SD/DD)	30		
BUS CAPTAIN NAME	MOHD ESA BIN OTHMAN			BUS ROUTE NUMBER			
THIRD PARTY CLAIM AGAINST	MS FIRST CAPI	TAL / CDG TAXI		BUS ADVERTS (Y/N)			
SECTION 1 : ASSESS	SMENT / REPAIR / SP	RAY PAINT (LABOL	JR COST)				
LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)						TOTAL COST	
TO REMOVE INSTALL O/S/R CORNER BUMPER						325	\$650.0
SPRAY PAINTING						320	
		LKK	Auto Consultants he	ence notify	7		
		the	Repairer of the follow	ving:			
		• To	resurvey before/after spra display damaged part(s) o	ly painting Suring resurvey			
Parts prices are subject to confirmation						 	\$90.3
No illegal modification(s) is allowed						-	
		• Su	oplementary item(s) must ubject to final approval fro	he resurveyed and	LABOUR TOTAL COST		\$1,380.3
				orn insurance Company			
SECTION 2 : RECOV	VERY OF ACCIDENT B	Ackn US (TOWING COST	owledged by Repairer				
		Date					
			TOTAL TOWING COS				
SECTION 3 : NUME	BER OF DAYS BUS IN I	WORKSHOP FOR SI	JRVEY & REPAIRS				
					DATE IN		
					DATE & TIME SURVEY		
				_	DATE OUT		
		BUS TYPE (SD / DD)	SD		TOTAL NUMBER OF DAYS		
			LOSS OF USE COST				\$600.0
	SUM	IMARY	7		Pasu		
	SECTION NO.	COST			He girsiarly		
	1	\$1,380.3	30				
	2	-			را ما الم	Ω	
1	1	1	1		I PV W	7 /	

\$600.00 \$1,980.30 TOTAL

18/12/2020@1215 Rosy after report