

ASS. REC. BY: Taufik

REF:

CS/CT120014291/Tig f3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. DMPCSNW00087642009Claims No. SNM20D204849C03

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$48K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 5J5566E Yr Regn: 242, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW Active hybrid 5.c.c 2479Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 197862 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA FZ92050C7 53129

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 18/12/20Survey held at 8K Auto Tuh Gurn.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/12/20@11.39am revised to Adeline Chng via Merimen.

Taufikh finalised LS \$4700, 3 days (Red \$6314.60, 57%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 25/06 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 2

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: MER-TPLump Sum / LS: 4700

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel : 6266 0555 Fax : 6266 3155

TO : CHINA TAIPING	DATE : 16-Dec-20
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	
 OWNER PARTICULAR	
NAME :	VEHICLE DETAILS
ADDRESS :	VEHICLE NO. : SJJ5566E
TEL. NO. :	MODEL / MAKE : BMW ACTIVEHYBRID
OWNER INSUANCE : INDIA	CHASSIS NO. : WBA7Z92030C753129
POLICY NO. : D18MPC0000151_02	ACCIDENT DETAIL
PERSON INCHARGE :	DATE : 14-Dec-20
	TIME : 08:40hrs

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT HEADLAMP RH	1	\$ 3,142.25	\$ at 3,142.25
2	FRONT HEADLAMP NOZZLE RH	1	\$ 174.90	\$ car 174.90
3	FRONT HEADLAMP LOWER BRACKET RH	1	\$ 221.95	\$ R 221.95
4	FRONT HEADLAMP TOP PANEL RH	1	\$ 155.60	\$ X 155.60
5	FRONT FENDER RH	1	\$ 888.15	\$ R 888.15
6	FRONT FENDER INNER SHIELD FRONT RH	1	\$ 135.67	\$ R 135.67
7	FRONT FENDER CHROME GARNISH RH	1	\$ 105.60	\$ X 105.60
8	FRONT BUMPER	1	\$ 1,456.10	\$ de 1,456.10
9	FRONT BUMPER SIDE CAMERA RH	1	\$ 687.60	\$ X 687.60
10	FRONT BUMPER PARKING SENSOR RH	1	\$ 245.60	\$ rw 245.60
11	FRONT BUMPER PARKING SENSOR RUBBER SEAL	4	\$ 8.00	\$ del 32.00
12	FRONT BUMPER PARKING SENSOR HOLDER	4	\$ 30.15	\$ del 120.60
13	FRONT BUMPER FOG LAMP RH	1	\$ 283.30	\$ car 283.30
14	FRONT BUMPER LOWER CENTER GRILLE	1	\$ 79.20	\$ R 79.20
15	FRONT BUMPER LOWER SIDE GRILLE RH	1	\$ 75.20	\$ de 75.20
16	FRONT BUMPER NOZZLE COVE LH/RH	2	\$ 47.85	\$ X 95.70
17	FRONT BUMPER SIDE RETAINER LH/RH	2	\$ LH X 35.60	\$ RH 71.20
18	FRONT BUMPER INNER SPONGE	1	\$ 60.50	\$ del 60.50
19	FRONT BUMPER REINFORCEMENT	1	\$ 719.50	\$ X 719.50
20	FRONT BUMPER LOWER UNDER COVER	1	\$ 185.80	\$ tn 185.80
			TOTAL PRICE	\$ 8,936.42
			LESS -5%	\$ (446.82)
			SUB TOTAL PRICE	\$ 8,489.60

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT HEADLAMP CLIPS SET RH	1	\$ 40.00	\$ 20.00 40.00
2	FRONT FENDER INNER SHIELD CLIPS SET RH	1	\$ 60.00	\$ 10.00 60.00
3	FRONT BUMPER CLIPS SET	1	\$ 80.00	\$ 30.00 80.00
4	FRONT BUMPER RIVET SET	1	\$ 60.00	\$ 10.00 60.00

TOTAL

\$ 240.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 750.00	450	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 750.00	450.	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 75.00	X	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REPLACED FRONT BUMPER PARKING SENSOR WITH DISTANCE SETTING AND SIDE CAMERA	\$ 280.00	30.	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 350.00	150	

TOTAL

\$ 2,285.00

QUOTATION SUMMARY

PAGE 03

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	8,729.60
TOTAL LABOUR COST	:	\$	2,285.00
TOTAL REPAIR COST	:	\$	11,014.60

APPROVED DETAILS

NO. OF REPAIR DAYS	:	DAYS
REPAIR UNDER	:	PART BY PART OR <u>LUMPSUM</u>
DATE / TIME OF SURVEY	:	Tanpin 9749 5747 / 67418434
SURVEYED BY / FROM	:	18/12/20 C 540 PL
CONTACT NUMBER	:	
FAX NUMBER	:	Tanpin C / Khantoran
EMAIL ADDRESS	:	
DATE / TIME OF RE-SURVEY	:	Resurvey after repair
EXCESS	:	3 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

771B

Vehicle Details

Vehicle No.:

SJJ5566E

Vehicle to be Exported:

No

Intended Deregistration Date:

17 Dec 2020

Vehicle Make:

B.M.W.

Vehicle Model:

ACTIVEHYBRID 5 3.0L AT D/AB SR HUD 4DR

Primary Colour:

Silver

Manufacturing Year:

2012

Engine No.:

12248070N55B30A

Chassis No.:

WBAFZ92030C753129

Maximum Power Output:

250.0 kW (335 bhp)

Open Market Value:

\$65,893.00

Original Registration Date:

22 Jun 2012

First Registration Date:

22 Jun 2012

Transfer Count:

0

Actual ARF Paid:

\$39,536.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

21 Jun 2022

PARF Rebate Amount:

\$21,744.00

Intended COE Rebate Details

COE Expiry Date:

21 Jun 2022

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$85,400.00

COE Rebate Amount:

\$12,904.00

Total Rebate Amount:

\$34,648.00

The information contained herein is correct as at 17 Dec 2020

OK