

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI20014096/Ktf3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	9: 19/01/2021	
			Cod	e: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 8895G	Veh. Inspected	SMT 2124D	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10008400/ST	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	18/12/2020	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES C180 (A)	c.c	1597	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	WDD2040452A493390	Colour	METALLIC BLACK	
	Odometer	112757 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	235/40 R18	BRIDGESTONE	7 mm	
	L/H Front Tyre	235/40 R18	BRIDGESTONE	7 mm	
	R/H Rear Tyre	235/40 R18	BRIDGESTONE	7 mm	
	L/H Rear Tyre	235/40 R18	BRIDGESTONE	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	. General Information				
	Accident Date	17/12/2020	Inspection Date	18/12/2020	
	Survey held at	THIAM HENG HUAT PTE LTD			
		176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: