

SERVICE ESTIMATE

84458 - C00001 SL: SERVICE SALES - PC

Mr Tan Chor Sen Christopher
61 Pavilion Place

Singapore 658397

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Tan Chor Sen Chri

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 18/12/2020
WIP No. . : 55959
Veh.In/Out:
*Tel.No. . : Mobile: 92707088
Reg.No. . : SKZ8526E
Reg.date .. : 04/02/2016
Mileage .. : 0
Chassis No: SAJAB4AG3GA905078

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT BUMPER, @9w BONNET, FRT RH FENDER, HEADLAMP RH, REPAIR FRT RH DOOR, A PILLAR RH @8w	0	5400.00	0		5,400.00 S	3600
800	TO SPRAYPAINT ON FRT BUMPER, BONNET, FRT RH FENDER, FRT RH DOOR, ETC	0	4800.00	0		4,800.00 S	3600
0031	TO REPLACE FRT RH RIM	0	50.00	0		50.00 S	/
419	WHEEL ALIGNMENT	0	280.00	0		280.00 S	/
280	TO FOCUS HEADLAMP	0	175.00	0		175.00 S	/
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	525.00	0		525.00 S	/
287	TO REMOVE, REPLACE FRT RH SUSPENSION PARTS	0	2100.00	0		2,100.00 S	1400
	COVER-BUMPER de	1.0 EA	1861.00			1,861.00 S	
	BRACKET-FEND RH Cra	1.0 EA	37.10			37.10 S	

SERVICE ESTIMATE

84458 - C00001 SL: SERVICE SALES - PC

Mr Tan Chor Sen Christopher

61 Pavilion Place

Singapore 658397

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Tan Chor Sen Chri

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 18/12/2020

WIP No. . : 55959

Veh.In/Out:

*Tel.No. . : Mobile: 92707088

Reg.No. . : SKZ8526E

Reg.date. : 04/02/2016

Mileage . : 0

Chassis No: SAJAB4AG3GA905078

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRACKET-FEND LH ?	1.0 EA	37.10			37.10	S
	GRILLE-RADIA X SVC	1.0 EA	473.50			473.50	S
	INSERT-FOAM ?	1.0 EA	57.50			57.50	S
	PANEL-NOSE X SVC	1.0 EA	97.30			97.30	S
	INSERT RH X SVC	1.0 EA	24.10			24.10	S
	INSERT LH X SVC	1.0 EA	24.10			24.10	S
	COVER WASHER RH ?	1.0 EA	42.70			42.70	S
	MESH-GRILLE RH ?	1.0 EA	256.60			256.60	S
	DUCT-AIR RH ?	1.0 EA	110.10			110.10	S
	BONNET PANEL X repair X	1.0 EA	1375.10			1,375.10	S
	MOUNTING-BRA .	1.0 EA	27.70			27.70	S
	LINER-WHEELARCH RH ?	1.0 EA	349.70			349.70	S
	JET-POWERWASH RH ?	1.0 EA	305.80			305.80	S
	HEADLAMP RH 50 /	1.0 EA	3641.80			3,641.80	S
	CROSSMEMBER X SVC	1.0 EA	728.00			728.00	S
	FRAME-SUPPOR 5 /	1.0 EA	453.40			453.40	S
	BRACKET RH X SVC	1.0 EA	69.00			69.00	S

SERVICE ESTIMATE

84458 - C00001 SL: SERVICE SALES - PC
 Mr Tan Chor Sen Christopher
 61 Pavilion Place

Singapore 658397

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Mr Tan Chor Sen Chri

Inv.No. . : B&P 0 Page 3
 Inv.date. : 18/12/2020
 WIP No. . : 55959
 Veh.In/Out:
 *Tel.No. . : Mobile: 92707088
 Reg.No. . : SKZ8526E
 Reg.date. : 04/02/2016
 Mileage . : 0
 Chassis No: SAJAB4AG3GA905078

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	REINFORCEMENT X SVC	1.0 EA	366.90			366.90	S
	FINISHER-VEN <i>na</i>	1.0 EA	215.30			215.30	S
	WHEEL-ROAD-ALLOY <i>sea</i>	1.0 EA	901.40			901.40	S
	ADHESIVE SEALER FL2 <i>na</i>	1.0 EA	709.60			709.60	S
	BODY PANEL SEALANT X SVC	1.0 EA	955.20			955.20	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Labour Total 13,330.00
Parts Total 13,120.00
Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Rene
Hp 9200068
6 days
18/12/2020 @ 1600
Resy before paint

Gross Total. 26,450.00
 Net..... 26,450.00
 GST @ 7.0% 1,851.50
 Total..... 28,301.50
 Paid..... 0.00
 Please Pay.. 28,301.50