

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 56927**
Date Estimated : **17/12/2020**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Song Wei
656B Jurong West St 61
#14-311

Singapore 642656

- ACCOUNT - 158

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY5575A	WBAJG12040EN492	31/01/2019	X1 sDrive18i	5112783

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper panel,make good tail end panel,boot lid and remove attachments to facilitates repair	2,550.00	0.00	2,550.00 ✓
To respray rear bumper,tail end panel and bootlid	2,500.00	0.00	2,500.00 ✓
# To replace front exhaust silencer include alignment and check leak	451.00	0.00	451.00 ✓
# To replace exhaust Cat convertor include alignment and check leak	451.00	0.00	451.00 ✓
To replace rear exhaust silencer including alignment and check leak.	451.00	0.00	451.00 ✓
To check electrical wiring system and lighting at the rear section.	150.00	0.00	150.00 ✓
To replace bootlid smart opener mounting, remove/install top and bottom sensor line include and conduct check for function.	561.00	0.00	561.00 ✓
To carry out body cavity preservation.	100.00	0.00	100.00 ✓
Sundries	150.00	0.00	150.00 ✓
# Grapheve Coating packages	400.00	0.00	400.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
SILENCER CLAMPING BUSH	54.60	1.00	0.00	54.60 ✓
# GASKET RING	30.60	1.00	0.00	30.60 ✓
# V BAND CLAMP	43.25	1.00	0.00	43.25 ✓
# HOLDER EXHAUST SYSTEM	28.75	1.00	0.00	28.75 ✓
# FRONT SILENCER	1,025.85	1.00	0.00	1,025.85 ✓
REAR SILENCER	1,184.25	1.00	0.00	1,184.25 ✓
TAILPIPE TRIM BLACK CHROME	113.85	1.00	0.00	113.85 ✓
# EXCH CATALYTIC CONVERTER CLOSE TO EN	2,118.50	1.00	0.00	2,118.50 ✓
# STEERING BOX HEAT RESISTANT PLATE	61.55	1.00	0.00	61.55 ✓
REAR BUMPER TRIM PANEL BOTTOM (BASI	206.85	1.00	0.00	206.85 ✓
MOUNTING SMART OPENER	45.75	1.00	0.00	45.75 ✓
RR BUMPER LH CORNER MOUNTING	143.35	1.00	0.00	143.35 ✓
REAR BUMPER PANEL PRIMED	907.90	1.00	0.00	907.90 ✓
# REAR BUMPER MIDDLE TRIM PANEL (PDC)	266.95	1.00	0.00	266.95 ✓
REAR BUMPER HEAT INSULATION	69.85	1.00	0.00	69.85 ✓

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

# EXPANDING RIVET BLACK	1.40	20.00	0.00	28.00	✓
# PLUG BLACK D=5MM	0.95	6.00	0.00	5.70	✓
#					

SUPPLEMENTARY ITEMS

Total Labour :	7,764.00
Total Parts :	6,335.55
Total Labour & Parts :	14,099.55
Deduction for Excess :	
Total Repair Costs less Excess:	14,099.55
GST @7%:	986.97
Grand Total :	15,086.52

CAR RENTAL=\$428.00

GIA SEARCH FEE=\$2.00

Supplementary for tail panel labor & spray include in Mi

Performance Motors Limited

A member of the Sirrie Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2 0020081-X



Final Report

CASH SALES

No. A 0244

Messrs:

$SJY\ 5575A\ (x_1)$

Date: 2 April 2021

Item	Description	Quantity	Unit Price	Amount
1.	TO POUSH & RECOAT WITH GRAPHENE COATING AS FOLLOW. BOTH SIDE DEAR FENDER, REAR BUMPER & TRUNK COVER.			SGD 400/-
			Total Amount	SGD 400/-

E. & O. E.

Authorised Signature

Received by