




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CS3/EQI20014114/R1qd3e2 Date: 28/04/2021 Code: EQI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YN 9478B	Veh. Inspected	SMS 6111U
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM20HO01911/JG	Excess (\$)	0.00
	Assign From	JANICE GOH	Assign Date	18/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLA180 URBAN	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WDC1569422J671735	Colour	WHITE
	Odometer	38590 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50Z R18	DUNLOP	6 mm
	L/H Front Tyre	235/50Z R18	DUNLOP	6 mm
	R/H Rear Tyre	235/50Z R18	DUNLOP	6 mm
	L/H Rear Tyre	235/50Z R18	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information				
	Accident Date	16/12/2020	Inspect Date / Time	22/12/2020 (11:12 AM)
	Survey held at	42 Toh Guan Road East #01-78		
	Repairer	MTM PERFORMANCE AUTO PTE. LTD.		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/EQI20014114/R1qd3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.