

ASS. REC. BY:

REF:

AIG/20014155KB

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HO 9278R Yr Regn: 12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius c.c. 1798

Colour

M.P. White / Red A/C: Insured / Std / NI / NA

Sp. Reading

203.99 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU-603077257

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

14/12/20

Rear

R/Bal.

7

mm

L/Bal.

7

mm

D.O.I.

15/12/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/1 83564.05

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9278R**AAD2012-**

Not Insured
Resurvey B4 paint
@ 3564.05

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 DEC 2020

SHD9278R

JTDKB3FU603077257

TOYOTA

PRIUS

14/12/2020

AIG

04/12/2018

	PART
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	COVER, REAR BUMPER, LOWER
1	RETAINER, REAR BUMPER SIDE, LH
1	FILLER, REAR BUMPER EXTENSION, LH
1	FILLER, REAR BUMPER EXTENSION, RH
1	SEAL, REAR BUMPER SIDE, LH
1	LENS & BODY, REAR COMBINATION LAMP, RH
1	LENS AND BODY, REAR LAMP, RH
1	PANEL SUB-ASSY, BODY LOWER BACK
1	PANEL SUB-ASSY, QUARTER, RH
1	LINER, REAR WHEEL HOUSE, RH
1	PANEL SUB-ASSY, BACK DOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	WEATHERSTRIP, BACK DOOR
1	SPOILER, SUB ASSY, REAR
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH
1	COVER, FLOOR UNDER, NO.1 (LH)
1	COVER, FLOOR UNDER, NO.2 (RH)
1	COVER, REAR FLOOR (CTR)

	LIST	
\$	Bulldo 442.60	✓
\$	su 332.70	X
\$	nulm 576.30	✓
\$	nu 15.40	✓
\$	su 116.50	X
\$	su 123.70	X
\$	nu su 123.70	✓
\$	su 88.50	X
\$	cm 451.80	✓
\$	cm 502.00	✓
\$	n 651.00	X
\$	n 871.50	X
\$	n 139.80	X
\$	n 1,147.80	X
\$	mjcm 925.60	✓
\$	su 372.30	} X
\$	su 1,575.40	
\$	su 242.50	
\$	su 242.50	
\$	n 61.00	
\$	n 61.00	
\$	su 175.10	
\$	su 241.90	
\$	su 229.90	
TOTAL	\$ 9,063.60	
25%	\$ 2,265.90	
	\$ 6,797.70	

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9278R

Special Nett

1SET PARKING AID	\$	fm 700.00	X
1SET REAR BUMPER CLIP	\$	nn 95.00	665a
2 WINDSCREEN SEALANT	\$	nn 150.00	} X
1 WINDSCREEN MOULDING	\$	nn 200.00	
1 WINDSCREEN INNER SPONGE SEAL	\$	nn 130.00	
1 REAR TAILGATE TOYOTA LOGO	\$	nn 47.90	
1 REAR TAILGATE WORDING 'PRIUS'	\$	nn 54.60	
1 REAR TAILGATE WORDING 'HYBRID'	\$	nn 54.60	
1 REAR TAILGATE STICKER "Trans-Cab"	\$	nn 80.00	
1 REAR TAILGATE STICKER "6555-3333"	\$	nn 80.00	
1 REAR BUMPER PROTECTOR	\$	nn 180.00	
1SET REAR FENDER LINER CLIP	\$	nn 85.00	
1SET REAR BUMPER RETAINER CLIP	\$	nn 85.00	} 155a
1 REAR NUMBER PLATE WITH HOLDER	\$	nn 140.00	
1SET TAILLAMP LOWER CLIP	\$	nn 55.00	155a
1SET TAILLAMP UPPER CLIP	\$	nn 55.00	155a
1 END PANEL TRIM CLIP	\$	nn 65.00	X
1 REAR SPOILER CLIP	\$	nn 70.00	X
TOTAL	\$	2,327.10	

TOTAL PARTS	\$	9,124.80
--------------------	-----------	-----------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$	nn 300.00	X
----	-----------	---

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	601
----	--------	-----

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	2,200.00	4001
----	----------	------

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	nn 380.00	X
----	-----------	---

Trans-cab Auto Services Pte Ltd**AAD2012-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9278R

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
Towing Fees	\$	nn	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	6601
To reinstall rear bumper parking sensor.	\$		170.00	501
To Check Electrical Lighting Concerned.	\$		170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	h	220.00	X
To replace, refix and top up coolant for radiator	\$	h	170.00	X
To lift-up / out engine with gear box and refit.	\$	h	440.00	X

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9278R

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ *nn* 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ *nn* 380.00 X**TOTAL \$ 10,290.00****Over All Total \$ 19,414.80****(PART-BY-PART) Repair Days***25 DAYS**2 1/2 days***For Official Use**

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD9278R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Dec 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B79724
Chassis No.:	JTDKB3FU603077257
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	04 Dec 2018
First Registration Date:	04 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Dec 2026
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	03 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$16,457.00
Total Rebate Amount:	\$27,142.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Dec 2020

OK