

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014219/EVF3E2

Date: 08/02/2021

REFERENCE

Insured/Claimant: DUFU INDUSTRIES SERVICES PTE LTD

Policy No: 2100452547

Date of Loss: 19/12/2020

Nature of Claim: OD

Claim No: 3385457091SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA3918K**

Make & Model: KIA OPTIMA, 1.7 D (A)

Engine No: G4NDFH092301

Reg. Date: 29/02/2016 (Man. Year: 2015)

Chassis No: KNAGU411MG5034644

Colour: Black

Odometer: 62280 km

Engine Capacity: 1999 cc

Market Value/New Car Price: S\$68,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Kumho 5 mm

Rear Left Side: Kumho 5 mm

Front Right Side: Kumho 5 mm

Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,531.60	1,441.60	90.00	5.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,610.00	1,040.00	39.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,181.60	3,051.60	1,130.00	27.02
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	3,581.60	2,451.60	1,130.00	31.55
+ GST 7.00/7.00% (S\$)	250.71	171.61	79.10	31.55
Nett Amount (S\$)	3,832.31	2,623.21	1,209.10	31.55

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 21/12/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
2	1		*HANDLE ASSY-DOOR OUTSIDE, LH	Missing	55.00 FL	*55.00 FL
3	1		*PAD-DOOR OUTSIDE HANDLE, LH	Missing	3.00 FL	*3.00 FL
4	1		*COVER-FR DR O/S HDL LH	Missing	25.00 FL	*25.00 FL
5	1		*PAD-DOOR O/S HANDLE REAR, LH	Missing	3.00 FL	*3.00 FL
6	1		*PANEL ASSY-REAR DOOR, LH	Dented	1,307.00 FL	*1,307.00 FL
7	1		*MOULDING ASSY-RR DR FRAME, LH	Necessary	132.00 FL	*132.00 FL
8	1		*GARNISH ASSY-RR DR FR FRAME , LH	Necessary	104.00 FL	*104.00 FL
9	1		*GARNISH ASSY-RR DR RR FRAME , LH	Necessary	126.00 FL	*126.00 FL
10	1		*MOULDING-RR DR OPNG W/STRIP MT	Not Necessary	22.00 FL	*- FL
11	1		*W/STRIP ASSY-RR DR BELT O/S LH	Not Necessary	78.00 FL	*- FL
12	1		*FILM-RR DR ANTI CHIPPING,LH (Supplementary)	Necessary	14.00 FL	*14.00 FL
13	1		*FILM- ANTI CHIPPING LH (Supplementary)	Necessary	8.00 FL	*8.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					1,907.00	1,797.00
- List Item Discount on L Items 20.00/20.00% (S\$)					375.40	355.40
Total Parts (S\$)					1,531.60	1,441.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW LHR DOOR. REPAIR LHR FENDER	New	1,600.00	600.00
2	RESPRAY LHR DOOR & LHR FENDER	New	700.00	700.00
3	REMOVE & REFIT LHR DOOR COMPONENT	New	120.00	120.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
Gross Labour Cost (\$\$)			2,650.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >