



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20014225/Utd3e2 Date: 04/01/2021 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJK 8785P	Veh. Inspected	SMF 9813B	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10008427/LA	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	21/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS PLUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDZS3EUX0J035962	Colour	RED	
Odometer	34190 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	7 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	7 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/12/2020	Inspection Date	22/12/2020	
Survey held at	TAN LIM MOTOR PTE LTD NO.1 DEFU LANE 6 SINGAPORE 539365			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	