

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 9548X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT RH SIDE PANEL,ALUMINIUM (SN)	TO REPAIR SEE LABOUR	933.30	-
1	COVER GRILLE RH (SN)	SERVICEABLE	76.25	-
1	RH GRILLE AIR INLET OPEN (LINES)(SN)	SERVICEABLE	116.45	-
1	RH FOG LAMP SUPPORT (SN)	SERVICEABLE	65.00	-
1	FRT BUMPER PANEL PRIMED (PMA/PDC)(SN)	DEFORMED	1,384.80	1,384.80
1	RH HEADLIGHT LED AHL HIGH (ICON LIG)(SN)	CRACKED	4,879.55	4,879.55
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
			7,605.35	6,414.35
	<u>LABOUR</u>			
	TO REPLACE BUMPER FRONT PANEL AND FRONT RIGHT SIDE PANEL.INCLUSIVE OF THE REPAIR OF FRT RH SIDE PANEL,ALUMINIUM.		2,550.00	1,700.00
	TO SPRAY PAINT BUMPER FRONT COVER AND FRONT RIGHT SIDE PANEL.		1,923.00	1,730.00
	TO REPLACE RIGHT HEADLIGHT AND REPROGRAMMING.		481.00	408.00
	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	150.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.		177.00	150.00
			5,308.00	4,138.00
	GRAND TOTAL		12,913.35	10,552.35

RECOMMENDED COST OF REPAIRS		10,552.35
LESS EXCESS		-750.00
NETT LIABILITY		9,802.35

Report Ref No. CS/UOI20014256/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X; Z.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.