



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI20014256/R1vf3e2	
			Date: 18/03/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SMJ 9548X
	Policy No.	DHOM120051092000	Coverage (\$)	0.00
	Claim No.	M12D14512101	Excess (\$)	750.00
	Assign From	JOSEPHINE WONG	Assign Date	22/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	BMW 520I LED NAV	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WBAJA12050BJ20916	Colour	BLACK
	Odometer	35023 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R19	MICHELIN	6 mm
	L/H Front Tyre	245/45 R19	MICHELIN	6 mm
	R/H Rear Tyre	245/45 R19	MICHELIN	6 mm
	L/H Rear Tyre	245/45 R19	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/12/2020	Inspection Date	01/02/2021
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE MARKET VALUE IS S\$176,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	