

REF: MSG / 7

Page 1 / 2

& B MOTOR REPAIRS SERVICES PTE LTD

SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

Mail : tbmotor@hotmail.sg

ss. Reg. No. : 199001597D

WITHOUT PREJUDICE

ONG HONG SEAFOOD ENTERPRISE PTE LTD

WOODLANDS LOOP #03-54 /56
3322

Estimate : ES003413

Date : 05/12/2020

Vehicle Num. : GBD2375K

Make/Model : TOYOTA DYNA

Chassis/Eng# :

Accident Date : 04/12/2020

Claim No. :

Reference :

Policy No. : 5118517360

Attention : Motor Claim Department

Not Authorized

11 Day @ 2050h

Resurvey After Paint

4 days

Quantity	Particular	Unit Price	Amount S\$
----------	------------	------------	------------

LIST ITEMS :

1	FRONT DOOR	1650.40
1	FRONT DOOR INNER LOCK RH	
1	FRONT DOOR GLASS OUTER MOULDING RH	
1	FRONT DOOR GLASS REGULATOR GEAR RH	233.20
1	FRONT DOOR GLASS REGULATOR GEAR MOTOR RH	
1	FRONT DOOR WEATHERSTRIP RH	278.40
1	FRONT DOOR TOP HINGE RH	
1	FRONT DOOR LOWER HINGE RH	
1	FRONT BUMPER	
1	FRONT HEAD LAMP R/H	
1 (R/H)	LOWER STEP BOARD GARNISH	275.80
1	FRONT WHEEL BEARING RH	
1	FRONT DOOR GLASS INNER CHANNEL R/H	
1	FRONT DOOR FRONT INNER RUBBER R/H	

List Total S\$:

25.00% Discount S\$:

LABOUR :

1. REMOVE & REFIX FRONT DOOR GLASS
2. SPRAY ANTI-RUST COATING
3. CHECK & REPAIR WIRING
4. SPRAY PAINT ON AFFECTED PORTIONS
5. LABOUR TO DO PANEL BEATING, WELDING AND REPAIR THE DAMAGED PORTIONS
6. REMOVE & REPLACE FRONT WHEEL BEARING
7. COMPUTER WHEEL ALIGNMENT

14	2,202.20	✓
R	423.50	X
SA	254.10	X
Dis	381.15	X
SA	783.48	X
139.20 in Dis / Ref	317.25	507.4
R	211.75	X
R	211.75	X
R	677.60	X
SA	1,058.75	X
Dis / Ref	508.20	✓
SA	296.45	X
SA	330.33	X
SA	68.00	X

7,724.51

1,931.13

5,793.38

60h	180.00	
30h	80.00	30h
20h	80.00	20h
40h	550.00	40h
30h	700.00	30h
20h	180.00	X
20h	120.00	X

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 2 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

SIONG HONG SEAFOOD ENTERPRISE PTE LTD

15 WOODLANDS LOOP #03-54 /56
738322

Attention : Motor Claim Department

Estimate : ES003413

Date : 05/12/2020

Vehicle Num. : GBD2375K

Make/Model : TOYOTA DYNA

Chassis/Eng# :

Accident Date : 04/12/2020

Claim No. :

Reference :

Policy No. : 5118517360

S/N	Quantity	Particular	Unit Price	Amount S\$
		8. SUPPLY AND APPLY THE REG ADDRESS STICKER		30.00
		Labour Total S\$:		1,920.00

2 cl.

SingDollars : Seven Thousand Seven Hundred Thirteen & Cents Thirty-Eight Only

E. & O.E.

Total S\$:

7,713.38


for T & B MOTOR REPAIRS SERVICES PTE LTD