

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Joel Goh

Date: 31 Dec 2020

## **Preliminary Advice**

Vehicle No	: SMP1812D	Accident Date	: 04/11/2020
Make	: VOLKSWAGEN BEETLE	Policy No.	: DMPPHQ19-007664
Assignment Date	: 22/12/2020	Excess	: S\$250.00
Date of Inspection	: 30/12/2020	Est. Duration of Repair	: 4
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (UBI) 320 UBI ROAD 3 SINGAPORE 408649		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,725.30
Revised Amount	:S\$	3,395.50
Check Items (Estimated)	:S\$	3,975.20
Total	:S\$	7,370.70

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	34,998.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,002.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TYRE IS IN SERVICEABLE CONDITION. BRAKE TESTED AND FOUND WITHOUT ANY ABNORMALITY.