

Stars AutoWorks

160 Sin Ming Drive
#06-21 Sin Ming AutoCity
Singapore 575722

STARS RENTAL & LEASING

160 Sin Ming Drive
#05-21 Sin Ming Drive
Singapore 575722

ESTIMATE

DATE : 21/12/2020
VEHICLE NO : SDV 62 H
MAKE/MODEL : Mit. Lancer EX
ACC DATE : 20/12/2020

PARTICULAR

AMOUNT S\$

NETT ITEMS:

- 1 1 REAR END PANEL
- 2 1 REAR END PANEL TOP GARNISH
- 3 1 REAR BUMPER
- 4 2 REAR BUMPER SIDE RETAINER
- 5 2 REAR BUMPER REFLECTOR
- 6 1 REAR BUMPER TOW COVER
- 7 1 REAR BUMPER REINFORCEMENT
- 8 1 REAR BUMPER TOP BEAM

Ry	681.70	2
my car	182.00	2
Ry	746.00	✓
Sn	75.80	X
	137.80	4
nd	45.90	✓
Ry	246.10	2
Di's	132.90	2
	2,248.20	
10%	224.82	
	2,023.38	

Less Discount:

SPECIAL NETT ITEMS:

- 1 2 REAR END PANEL TOP GARNISH CLIP
- 2 10 REAR BUMPER CLIP
- 3 1 REAR REVERSE SENSOR

1 REAR NUMBER PLATE

Mr	10.00	2
Mr	50.00	✓
CM	350.00	200/2
	410.00	
nd	50.00	45/2

LABOUR CHARGES:

- 1 TO CHECK WIRING
- 2 TO TUFF KOTE
- 3 TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING
- 4 TO REMOVE/REFIX REVERSE SENSOR
- 5 TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS
- 6 TO SPRAY PAINTING ON AFFECTED AREA

50.00	152
250.00	301
150.00	60
100.00	50
1,000.00	500
1,000.00	450
2,550.00	

GRAND TOTAL: 4,983.38

Singapore Dollars: Four Thousand Nine Hundred And Eighty Three And Cents Thirty Eight Only.

STARS AUTOWORKS

Reg No: 53398222K
160 Sin Ming Drive
Sin Ming AutoCity #08-14
Singapore 575722

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: