

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation

DATE : 12.01.2021
 VEH NO : SKR104J
 MODEL : Volkswagen Golf
 D O A : 22.12.2020
 YR REF : SCN4888U

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKR104J (VOLKSWAGEN GOLF)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>torn</i>	1	1,079.00 ✓
2	Front Bumper Side Holder - RH <i>new</i>	1	55.00 ✓
3	Head Lamp - RH <i>new</i>	1	694.00 X
4	Front Fender - RH <i>Dented</i>	1	725.00 ✓
5	Front Fender Inner Shield - RH <i>Deformed</i>	1	214.00 ✓
6	Front Door - RH <i>Dented</i>	1	1,447.00 ✓
7	Front Door Weatherstripe - RH <i>new</i>	1	241.00 ✓
8	Front Door Lower Hinge - RH <i>new</i>	1	129.00 X
9	Front Wheel Rim - RH <i>cut</i>	1	1,314.00 700(SN)
10	Front Lower Arm - RH <i>3 new</i>	1	377.00 +
11	Front Knuckle Arm - RH <i>3 new</i>	1	691.00 X
12	Front Wheel Hub C/w Bearing - RH <i>3 new</i>	1	576.00 X
13	Front Shock Absorber - RH <i>3 new</i>	1	367.00 X
			7,909.00
Less 10%			(790.90)
			\$ 7,118.10

S/NETT ITEMS

1	Front Bumper Clips <i>new</i>	1 set	\$ 50.00 30
2	Front Fender Inner Shield Clips - RH <i>new</i>	1 set	\$ 30.00 ✓
3	Front Tyre - RH <i>3 new</i>	1	\$ 280.00 X
			\$ 360.00
Total Parts			\$ 7,478.10

LABOUR CHARGE

RE : ESTIMATE FOR ACCIDENT REPAIR SKR104J (VOLKSWAGEN GOLF)

1	To knocking & pull out front RH portion & renew above parts	\$	1,000.00 600
2	To putty & spray up paint works	\$	1,000.00 600
3	To check wiring	\$	50.00 30
4	To transfer front door fittings	\$	150.00 80
5	To spray tuff coat	\$	150.00 50
6	To dismantle front undercarriage	\$	350.00 +
7	To perform wheel alignment	\$	150.00 80
Total Labour		\$	2,850.00
Grand Total		\$	10,328.10

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 5584.90
L/S' 4450
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: