

Jasper Chua (LKK Auto)

From: Trident Auto <tridentauto.claims@gmail.com>
Sent: Wednesday, 24 February 2021 11:58 AM
To: Jasper Chua (LKK Auto)
Cc: Admin A
Subject: Re: AIGENCRYPT Liability Clearance - Accident Involving SBP8138B & SLF8285T ***
LKK REF: CC4/AIG20014325/ba3 (LOD Submission)
Attachments: 8. FINAL INVOICE.pdf

Without Prejudice

Dear Sir/Madam,

We are claiming as per below:

Cost of Repair	\$5,600.00 (L/sum)
Loss of Rental	\$1,620.00 (9 days x \$180)
LTA Search	\$7.45
Total	\$7,227.45

Enclosed the relevant documents of our client's claims.

Please look into this matter and revert for the settlement as soon as possible.

Warmest Regards,
ZHE CHIAN

Trident Auto Service Centre Pte Ltd
8 Kaki Bukit Ave 4 #02-44 Premier @ Kaki Bukit
Singapore 415875
T (65) 6344 1918 F (65) 6744 9778

DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. The sender shall not be liable for any loss or damage caused by viruses transmitted by this e-mail or its attachments. As the integrity of this message cannot be guaranteed, The sender shall not be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of TRIDENT AUTO SERVICES PTE LTD.

On Tue, Dec 29, 2020 at 3:23 PM Jasper Chua (LKK Auto) <jasperchua@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Sirs/Madam,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement. Please note that this e-mail is on without prejudice basis which

TRIDENT AUTO SERVICE CENTRE PTE LTD

8 Kaki Bukit Ave 4, #02-44 Premier @ Kaki Bukit (Gate 1)
Singapore 415875

AUTHORIZATION TO ACT

I, GC DAIGOU ("the third party claimant")
of BLK 917 JURONG WEST ST 91 #05-150, NANYANG EMERALD (S) 640917 (address),
owner of SBP 8138B (vehicle no.)
hereby authorize Trident Auto Service Centre Pte Ltd ("the
workshop") to act for me with respect to my claim for repair costs and / or rental and / or loss of use
("claim") for my vehicle no. SBP8138B that was damaged pursuant to the accident
which occurred
on 19/12/2020 (date) along KENT VALE ROAD
(location) involving vehicle no SLF8285T ("the accident").

I further authorize the workshop to sign the discharge voucher on my behalf to settle my above
mentioned claim in a manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in favour of the
workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other
vehicle/s is concerned.

Dated this 21 day of 12 (month) 20 20 (year)




Signed by "the third party claimant"
Policyholder's Signature only
& Company Chop - (if registered under a company)




Signed by "the workshop"

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-44
Premier @ Kaki Bukit (Gate 1)
Singapore 415875
Tel: 63441918

Date : 21/12/2020
Vehicle : SBP8138B
Make/Model : Toyota Alphard 2.5S
ORD : 2015
Chassis : AGH300013034
ODO : 236283
ACC Date : 19/12/2020

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way, #09-16 AIG Building
Singapore 079120

Final Invoice

S/N	Qty	Description & Specification	Amount S\$
<u>List Items</u>			
1	1	Tailgate	\$1,718.00
2	1	Tailgate 'ALPHARD' emblem	\$96.40
3	1	Tailgate lock w/auto motor	\$415.80
4	1	Tailgate w/stripe	\$335.20
5	1	Tailgate inner trim board	\$526.00
6	1	Rear w/screen moulding top	\$58.00
7	1	Rear w/screen moulding bottom	\$58.00
8	1	Rear w/screen moulding LH	\$45.00
9	1	Rear w/screen moulding RH	\$45.00
10	1	Rear bumper	\$1,146.80
11	1	Rear bumper tow cover	\$60.40
12	1	Rear bumper side retainer LH	\$77.10
13	1	Rear bumper side retainer RH	\$77.10
14	1	Rear bumper reverse sensor inner LH	\$272.60
15	1	Rear end panel	\$745.20
16	1	Rear end panel top garnish	\$259.80
			Less 25%
			List Total \$1,484.10
<u>Supplementary Items</u>			
1	1set	Reverse Camera	\$400.00
			S/Nett Total \$400.00
<u>S/Nett Items</u>			
1	1set	Tailgate inner trim board clips	\$30.00
2	1set	Rear w/screen sealant	\$40.00
3	1set	Rear w/screen inner seal	\$30.00
4	1set	Rear bumper clips	\$30.00
5	1set	Rear bumper reverse sensor o-ring	\$40.00
6	1set	Rear end panel sealant	\$60.00
7	1set	Rear end panel top garnish clips	\$20.00
			S/Nett Total \$250.00
<u>Labour</u>			
1		To cut, weld rear end panel, to replace tailgate assy, to repair rear floor panel and re-align on all accident affected areas	\$800.00
2		To putty and respray on rear accident portion	\$800.00
3		To check rear lighting and wiring	\$30.00
4		To apply anti-rust corrosion on rear affected areas	\$60.00
5		To remove and refit rear w/screen	\$120.00
6		To transfer tailgate mechanism to new tailgate	\$80.00
7		To remove and refit rear garnish, upholstery etc to assist repair	\$60.00
			Labour Total \$1,950.00
			Grand Total \$7,052.30
			L/S Less 20% \$1,410.46
			L/S Grand Total \$5,641.84
			Finalized Amt \$5,600.00

Trident Auto Service Centre Pte Ltd

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 22 Dec 2020 / 10:15:41

Receipt Date/Time : 22 Dec 2020 / 10:15:41

Tax Invoice/Receipt

Receipt No. : ITNET-00000-201222-000965

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLF8285T				
As at 19 Dec 2020/14:55:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLF8285T Enquiry Fee 20201222101249135440	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
454750XXXXXX9785		eNETS Credit Card		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.