

REPAIR ESTIMATE*

VEHICLE NO SHC153G

DATE 21/12/20

MAKE :

MODEL : HYUNDAI IONIQ G2

/CHIANG /AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			am ✓ \$418.30
1	FRONT BUMPER GRILLE LH			am ✓ \$186.90
1	FRONT DAYLIGHT LH			X \$642.50
1	FRONT BUMPER BRACKET LH			X \$35.00
1	HEADLAMP ASSY LH			X \$1,993.65
1	HEAD SUPPORT PANEL			X \$949.30
1	FRONT BUMPER CTR MOULDING			X \$186.90
1	FRONT LH FENDER			RY \$588.80
1	FRONT FENDER SHIELD LH			m ✓ \$164.70
1	FENDER EMBLEM BLUE -DRIVE			na ✓ \$26.60
1	FRONT RH WHEEL COVER LH			cut ✓ \$346.40
10	FRONT BUMPER CLIPS			na X \$22.00
	SUB TOTAL		1296.70	\$5,561.05
	20.00%			\$1,112.21
	DISCOUNTED TOTAL		20% 1057.36	\$4,448.84
	Labour Charge			
	Panel Beating		Labor - 400	\$700.00
	Spray painting		Spray - 400	\$600.00
	Check Lighting			\$60.00
	Remove/refix A/c condenser & charge gas		30	\$60.00
	TOTAL LABOUR		910 na	\$1,480.00
	ESTIMATE TOTAL		\$1947.36	\$5,928.84
	Toughin 97495449 wr 22/12/2004 pm toughin c / hants.com 2-3 days Resurvey before paint			
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.