

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 24 Dec 2020

Preliminary Advice

Insured Vehicle No	: GBJ3003X		
TP Vehicle No	: SLQ6162U	Accident Date	: 19/12/2020
Make	: TOYOTA WISH	Assignment Date	: 23/12/2020
Date of Inspection	: 23/12/2020	Est. Duration of Repair	: 7
Inspection At	: AP AUTOMOTIVE SERVICES PTE LTD (HQ) BLK 9006 TAMPINES STREET 93, #01-202 SINGAPORE 528840		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,908.40
Revised Amount	:S\$	15,760.18
Check Items (Estimated)	:S\$	6,199.55
Total	:S\$	21,959.73

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on wp