

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 05 Jan 2021

## **Preliminary Advice**

Insured Vehicle No	: SMF8907X		
TP Vehicle No	: GBH1444E	Accident Date	: 25/12/2020
Make	: NISSAN NV200	Assignment Date	: 04/01/2021
Date of Inspection	: 29/12/2020	Est. Duration of Repair	: 5
Inspection At	: ASIA MOTORSPORTS SOLUTION PTE LTD (HQ) 37A EVERITT SINGAPORE 428586		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,845.20
Revised Amount	:S\$	4,387.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,387.48
Lump Sum Repair	:S\$	3,500.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : survey on wp