



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: LOH CHEE HENG		Ref: CS3/AIG20008082/Utd3s2-1 Date: 29/12/2020 Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLZ 2507M	Veh. Inspected	SY 800B
Policy No.	1800042897	Coverage (\$)	0.00
Claim No.	9820814538SG	Excess (\$)	0.00
Assign From	LOH CHEE HENG	Assign Date	23/12/2020
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ E 250C (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2120472A359178	Colour	BROWN
Odometer	157296 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	245/45 R17	GOODYEAR	6 mm
L/H Front Tyre	245/45 R17	GOODYEAR	6 mm
R/H Rear Tyre	245/45 R17	GOODYEAR	6 mm
L/H Rear Tyre	245/45 R17	GOODYEAR	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	23/07/2020	Inspection Date	05/08/2020
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	