Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSa 64796624 (Motorra

(AfterSales) (Motorrad)

2 4 DEC 2020

VALUE

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 1 of 5 57020 : b1 stimate No. : 24/12/2020 ate Estimated Chua Kee Sin repared By

219 - ACCOUNT -ESTIMATE REPAIR FOR -India Int'L Insurance Pte Ltd hoo Kok Wee 64 Cecil Street 5 West Coast Road #04-05 IOB Building 05-17 Singapore 049711

ingapore 127365

MILEAGE MODEL REGN. DATE CHASSIS NO. EGN. NO. 0 X3 sDrive20i 28/09/2020 WBATS720009C71276 MV3775H

VALUE DESCRIPTION 3,400.00 Replace rear bumper include remove attachment etc and repa ir on rear boot lid include remove attachment etc and repair on accident area 2474. / 2,749.00 Painting rear bumper, rear boot lid and tail end panel 177.00 To check electrical wiring system and lighting at the rear section for proper function. 271.00 To remove and install boot compartment carpet and garnish to facilitate repair. 531.00 To replace rear exhaust silencer including alignment system and conduct check for leak. (451) 531.00 To replace front centre exhaust silencer including alignment and conduct check for leak. 150.00 Sundries

7,809.00 Total Labour 1:

PRIC QTY DESCRIPTION 102.35 102.35 VIBRATION ABSORBER 38 HZ 33.75 33.75 1 RUBBER MOUNTING 58.65 58.65 TRANSMISSION BRACKET 38.15 38.15 REAR SILENCER LH BRACKET / 24.80 24.80 RR SILENCER BRACKET 44.00 44.00 SWING SUPPORT ? TAILPIPE TRIM CHROME D=90MM / CA. 248.00 2 124.00 1.372.95 1,372.95 FRONT SILENCER 1,346.70 1,346.70 REAR SILENCER

REAR BUMPER GARRIER REAR BUMPER BOTTOM REINFORCEMENT 1,555.40 REAR BUMPER PANEL PRIMED (X LINE PM 1,555.40

Supplum try.

WORKSHOP QUOTATION

GST REG NO : M2 - 0020081 - X

Quotation No : 0000574032 Date 11/01/2021 Time 18:32:56 Page A Name Partsman p97lomi Del Doc 004097126 del Year STK PDC ISS. SELLING NET PART NUMBER CT AT SOH OTY PRICE PRICE LH BUMPER GUIDE CA 1 61.65 07147311312 C CLIP FOR PLASTICAL P 61.65 1.10 51127400665 LH SIDE GUIDE FORCE PO7147401727 EXPANDING RIVET P 6.60 58.55 58.55 07147401727 2.65 7.95 51127400678 REAR UNDERRIDE GUA DE P 234.00 234.00 51757404241 REAR END UNDERBODY DE P 76.05 61357391042 SENSOR WIRE FOR SMCLE 76.05 46.55 61357391043 SENSOR WIRE FOR SMC P 46.55 51.20 51.20 52208133466 PLUG BLACK D=5MM AU 6 .95 5.70

16

3A Signature ite .me

hicle No

51777171004

ıstomer's Name · Contact Person

Parts Total : 570.65 Labour Charges :

Sub Total : Add 7% GST :

1.40

22.40

TOTAL AMOUNT :

te:(1) The above quotation is based on visual inspection only and may change based on further checks.

- (2) The validity of this quotation is 14 days from the above date.
- (3) Parts are subject to availability.
- (4) Any prices change is without prior notice.

EXPANDING RIVET BLEW

the quotation is acceptable to you, please confirm your authorization for to proceed with the job on the understanding that prior approval will be ained from you before we carry out any further repair or replacement of s that will extend the total charges beyond the sum stated.

WORKSHOP QUOTATION

Date

GST REG NO : M2 - 0020081 - X

SMV: 3775H

hicle No

A Name :		40	Time Page Partsman Del Doc	:	09:41 p9710 00409	1 mi
/N PART NUMBER ** ******* 1 33306874406 2 51487407764 3 51487394801	DESCRIPTION CT ********* REAR AXLE CARRIER OF REAR SILENCER HEAT REAR SILENCER LH I	STK PDC AT SOH *** *** P P	QTY P *** ***** 1 1,86	LING RICE **** 5.20 0.75 0.75	DIS % ****	NET PRICE ******* 1,865.20 70.75 70.75

16/01/201

Α	Signature	:	
te		:	
mе		•	

stomer's Name Contact Person Parts Total : 2,006.70 Labour Charges :

Sub Total : Add 7% GST :

Quotation No : 0000574398

14/01/2021

TOTAL AMOUNT :

- te:(1) The above quotation is based on visual inspection only and may change based on further checks.
 - (2) The validity of this quotation is 14 days from the above date.
 - (3) Parts are subject to availability.
 - (4) Any prices change is without prior notice.

the quotation is acceptable to you, please confirm your authorization for to proceed with the job on the understanding that prior approval will be ained from you before we carry out any further repair or replacement of

Performance Motors Limited



1					Sand Sand
1		FACSIM	ILE MESSAGE		
DATE	14 Jan 2021	TIME	·		
INS	India International	FAX N NO OI	F PAGES		
SUV ATTN	Guo Qiang	FAX N	10		
МСА	Chua K S	FAX N			
I	f the fax is not received	d in order, please	e do call CSA. Thank y	/ou	
Dear S	irs,				
	mentary repair for BM Registration No.	W <u>X3</u> SMV3775H			
Vehicle	e Chassis No.	9C71276			
Supple	ementary Parts to re	place YES	Refer to attachme	nt	
	Parts / Lab	our Descript	tion *	OTY	Prices

Parts / Labour Description *	QTY	Prices
Reference to part quotation #574398		\$2,006.70
To replace rear axle carrier les	Net	\$1,328.00
To check steering geometry and conduct wheel alignment in accordance with BMW specification. (1x) $\kappa \omega$	457	\$531.00
equest for additional 2 work days		
(Colore		
Define		
Ţ.		
1401/2021		
	Total =>	\$3,865.7

^{*} All of the above which are highlighted will be considered as agreeable if there is no objection and/OR subsequence amendment within 3 work days.