

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL INV No. AC2100004

64 CECIL STREET INV Date 04/01/2021

#05-02 IOB BUILDING Reference CS3/III20014450/Qvd3e2

SINGAPORE 049711 Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SKK 1080Z

Insured Veh. SHD 4271S

Claim No.

Policy No.

Accident Date 22/12/2020

Inspection Date 24/12/2020

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 24.12.2020 12.53pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM