
BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group



MS First Capital Insurance Limited c/o LKK Auto Consultants Pte Ltd



Your Ref

D20005211MFSH

Our Ref: DS/2364475/SMG803J

"Without Prejudice"

Date: 7 April 2021

Subject: ACCIDENT INVOLVING VEHICLES SMG803J & SHC2458P ON 18/12/20

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows: -

Cost of Repair : \$ 20,035.11

Excess

:\$-

Loss of Use : \$ 480.00 (\$80*6 days)

GIA/LTA Search : \$ -

:\$-

Loss of Rental: \$ -

Others Total

: \$ 20,515.11

A copy of each of the following supporting documents is enclosed:

1. Copy of Final Repair bill Performance Motors Limited

2. Original Letter of Authorisation

3. Certificate of Insurance

1800-Call-BMW (1800-2255-269) www.pml.com.sg

303 Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel Sales 6319 0100 Tel Aftersales: 6319 0111 Fax 6474 7770

315 Alexandra Road Sime Darby **Business Centre** Singapore 159944 Tel Sales 6319 0511 Tel Aftersales 6319 0527 Fax 6479 6624

Kampong Arang Rd East Coast Centre Singapore 438180 Tel Aftersales 6319 0888 Fax 6344 1332

Registered office 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942

Co. Reg. No:

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Evelyn Chan / Mr Suhaimi at 6319-0175 / Fax.

6479-4601 or email to pml-pbsp@simedarby.com.sg.

Yours sincerely

Cresendo Lagman

Customer Service Manager, Body & Paint

Service Manager – Body & Paint



Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-00200

303, Alexandra Road Sime Darby Performa Singapore 159941 Tel. 63190100 (Sale 63190111 (Afte Fax. 64747770

280. Kampong Arang East Coast Centre Singapore 438180 Tel. 63190888 (Aft Fax. 63449773 315. Alexandra Road Sime Darby Business Singapore 159944 Tel. 63190528 (63190533/530 (Fax. 64796601



SERVICE TAX INVOICE

Repair Order No. : B1 1524440 Page No. : 1 of 2

Invoice Number: 2364475 / WSB Date IN : 18/01/2021

Invoice Date 31/03/2021

Motor Claim Advisor: Han Kwan Yong Payment Terms : 30 Days From Invoice Invoice By Mahamod Bin Mohd Sanif

- CUSTOMER INFORMATION -- INVOICE TO -303

Mr Chou Siaw Liang MS First Capital Insurance Limited

7 One-North Gateway 6 Raffles Quay

#03-24 #21-00

51127480086 REAR BUMPER PANEL PRIMED (LINES PDC

51127477978 REAR BUMPER TRIM STRIP (BLACK)

51127300815 REAR BUMPER CARRIER

51148209932 GROMMET

51148219237 PLAQUE 74MM

Singapore 048580 Singapore 138642

REGN. NO. REGN. DATE CHASSIS NO. MODEL MILEAGE 216I AT SMG803J 21/11/2018 WBA2X92080VD11460 42416

DMG0030	WBAZA92080VDII400 ZI/II/2018 =====			42410
	LABOUR 1			NETT
	To replace rear bumper, boot lid including to knock out tai			3,400.00
	I panel and to moke good front bumper			
	To respray front bumper, rear bumper, boot lid and tail pane			3,334.00
	1			
	To carry out body cavity preservation.			100.00
	(Per panel).			
	To transfer rear windscreen glass to new boot lid.			676.00
	To conduct water leak tests.			75.00
	To remove and install boot compartment carpet and garnish			231.00
	to facilitate repair.			
	To transfer lock mechanism to new bootlid.			451.00
	To transfer PDC assembly parts and connect to new			150.00
	bumper.			
	To check electrical wiring system at the front and rear			250.00
	sections.			
	Sundries			150.00
	INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.			0.00
	DATE OF ACCIDENT: 18.12.2020. 3RD PARTY CAR: SHC2458P.			
	YOUR REF NO: D20005211MFSH.			
	VEHICLE WAS SURVEYED BY RASUL FROM LKK CONSULTANT			
	ON 18.01.21@1220HRS. AUTHORISED BY RACHEL WU LI MEI			
	FROM MS FIRST CAPITAL VIA EMAIL ON 24.12.2020.			
	PROPOSE LOSS OF USE = \$80X6. THE AMOUNT IS SUBJECTED			0.00
	TO INCLIDANCE COMPANY CONFIDMATION			
	INSURANCE COMPANY CONFIRMATION.			
		Tot	cal Labour 1:	8,817.00
			Retail	:
Code	PARTS	Qty_	Price	NETT
41007317766	TRUNK LID	1	1,216.40	1,216.40

1,050.65

460.40

88.20

0.80

71.95

1,050.65

460.40

88.20

1.60

71.95

1

1

1

2

1

Performance Motors Limited

Co. Reg. No. 197401559W GST Reg. No M2-00200

303, Alexandra Road Sime Darby Performa Singapore 159941 Tel. 63190100 (Sale 63190111 (Afte Fax. 64747770

280, Kampong Arang East Coast Centre Singapore 438180 Tel. 63190888 (Aft Fax. 63449773 315. Alexandra Road Sime Darby Business Singapore 159944 Tel. 63190528 { 63190533/530 { Fax. 64796601 {



SERVICE TAX INVOICE

Repair Order No. : 2 of 2 : B1 1524440 Page No.

Invoice Number : 2364475 / WSB : 18/01/2021 Date IN

Invoice Date : 31/03/2021

Motor Claim Advisor: Han Kwan Yong Payment Terms : 30 Days From Invoice

Motor Clai 	im Advisor: Han Kwan Yong	Payment Terms Invoice By		0 Days From Inv Ahamod Bin Mohd	
83192211217	(DG) CLEANER R1 (100ML)		1	26.15	26.15
83192289285	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)		2	131.55	263.10
83199407777	(DG/SL)ADHESIVE PRIMER VP 206 (30ML		1	27.85	27.85
51127376925	RR BUMPER LH INNER SIDE GUIDE		1	61.65	61.65
61357932682	CONTROL UNIT SMART OPENER		1	497.05	497.05
66209283203	DECOUPING RING PDC TORQUE CONVERTER		3	5.15	15.45
51377164933	HOOK AND LOOP FASTENER		4	2.85	11.40
51127348299	SUPPORT		1	45.75	45.75
51127376926	RR BUMPER RH INNER SIDE GUIDE		1	61.65	61.65
51487328411	REAR BUMPER HEAT INSULATOR		1	60.90	60.90
51137467461	FRT LH GRILLE (SPORT)		1	113.15	113. 1 5
51137467462	FRT RH GRILLE (SPORT)		1	113.15	113.15
51747473906	AIR DUCT		1	271.95	271.95
51117477009	IMPACT ABSORBER TOP		1	49.50	49.50
51127300785	RR BUMPER LH SIDE GUIDE		1	61.65	61.65
64229315933	REAR VENTILATION LH		1	29.55	29.55
66209283760	ULTRASONIC SENSOR IMPERIALBLAU(WA89		2	371.20	742.40
07149174618	BLIND RIVET NUT M6		3	2.70	8.10
18328654542	EXCH CATALYTIC CONVERTOR CLOSE TO E		1	2,118.50	2,118.50
18308627284	REAR SILENCER		1	1,015.05	1,015.05
18308632361	MUFFLER CLAMP D=65.2MM		1	42.00	42.00
18308682297	TAILPIPE TRIM BRIGHT CHROME		1	119.55	119.55
18307560778	SILENCER CLAMPING BUSH		1	54.60	54.60
18308617370	HOLDER EXHAUST SYSTEM		1	28.75	28.75
18307606136	V BAND CLAMP		1	43.25	43.25
18307581970	GASKET RING		1	30.60	30.60
32105A01AF7	STEERING BOX HEAT RESISTANT PLATE		1	65.65	65.65
18308627212	FRONT SILENCER		1	1,025.85	1,025.85
51777171004	EXPANDING RIVET BLACK		10	1.40	14.00
			To	tal Parts :	9,907.40
Tahaur Cha	2 CC 7 00 Total	Inhoun C Dayta	Chas		49 724 40

Labour Charges	:	8,667.00	Total Labour & Parts Charges	:	S\$	18,724.40
Parts Charges	:	9,907.40	Less Insurance Excess	:	S\$	0.00
Lubricant/Misc	:	150.00	Invoice Total Amount Exclude GST	:	S\$	18,724.40
			GST @ 7%	:	S\$	1,310.71
			Invoice Total Amount Include GST	:	S\$	20,035.11

Computer generated invoice. No signature is required. Amount Payable Include GST S\$ 20,035.11

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service. No complaints will be entertained unless reported within seven (7) days of the date of this invoice. For credit purchases, interest @1% per month will be debited on overdue amounts.



Performance Motors Limited

A member of the Sime Darby Group

Name:

NRIC No.:

HAN KWAN YONG

Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941




LETTER OF AUTHORISATION

ACCIDENT INVOLVING & MG8037 & SHC2458P ON 18/12/2020
I, Mr. Chou Scaw Loag owner of Vehicle Registration No. SMG 8037 hereby authorise Performance Motors Limited to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.
I further authorise Performance Motors Limited to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.
I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.
I further confirm that the acceptance by Performance Motors Limited of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.
Signed by: Name: CHOU SIAW LIANG (Date) 21/12/2020 NRIC No.: 81739903 I
In the presence of:

(Date) 2//12/2020

FORM B1 VERSION 1 - SEPT 2017





AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore) (65) 6880 4888 (International)

(65) 6880 4740

☑ customer.care@axa.com.sg

www.axa.com.sg

Certificate of Insurance

account number 14235

-Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 -Road Transport Act, 1987 (Majaysja) -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name

CHOU SIAW LIANG

Certificate number

GA419902 / 1

Cover Plan name

Comprehensive PML

Chassis number Engine number

WBA2X92080VD11460 41585469B38A15A

NCD applicable

50% SMG8031

Vehicle registration number

Period of Insurance from 21/11/2020 to 20/11/2022 (both dates inclusive) Finance loan company

Persons or classes of persons entitled to drive*

(a) The Policyholder

(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes,

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Basic Own Damage Excess

SGD 600.00

Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

\$2500 for undeclared Young and Inexperience Driver(s)

\$2000 for Named Driver(s) with driving experience of less than 1 year on the relevant class of driving licence.

\$1500 for Named Driver(s) who are age 21 years old and below with driving experience of 1 year or more on the relevant class of driving licence.

\$1000 for Named Driver(s) who are age 22 years old to 26 years old with driving experience of 1 year or more on the relevant class of driving licence.

Additional clauses & endorsements to your policy

Nil

1/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.