

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

23/12/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1

Veh # :- SKZ5084H

Veh Model :- HONDA VEZEL

Estimate# :- CK421364

Claim # :-

ACC. Date :- 22/12/20

Terms :- C.O.D Days

Remarks :-

Alan 96869276

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	FRONT BUMPER <i>de / ? 4</i>	1	PC	810.00	810.00
2.	FRONT BUMPER REINFORCEMENT	1	PC	305.00	305.00
3.	FRONT GRILLE BASE <i>? cm</i>	1	PC	480.00	480.00
4.	FRONT GRILLE OUTER MOULDING <i>cm</i>	1	PC	320.00	320.00
5.	FRONT GRILLE LOGO <i>na</i>	1	PC	60.00	60.00
6.	FRONT BUMPER LOWER SPOILER <i>de</i>	1	PC	413.00	413.00
7.	FRONT BUMPER SIDE RETAINER <i>X su</i>	2	PCS	25.00	50.00 X
8.	BONNET <i>bt</i>	1	PC	634.00	634.00
9.	FRONT BUMPER CLIPS <i>na</i>	20	PCS	5.00	100.00
10.	REAR BUMPER <i>de</i>	1	PC	780.00	780.00
11.	REAR BUMPER LH & RH <i>LH-cut / RH-repair (no damage photo)</i>	2	PCS	155.00	310.00 X
12.	REAR BUMPER REFLECTOR LAMP <i>X su</i>	2	PCS	156.00	312.00 X
13.	REAR BUMPER CLIPS <i>na</i>	10	PCS	5.00	50.00
14.	TAILGATE <i>bt</i>	1	PC	910.00	910.00
15.	TAILGATE GARNISH <i>cut</i>	1	PC	195.00	195.00
16.	TAILGATE (VEZEL) EMBLEM <i>na</i>	1	PC	50.00	50.00
17.	TAILGATE (HYBRID) EMBLEM <i>na</i>	1	PC	58.00	58.00
18.	TAILGATE LOCK <i>cut</i>	1	PC	59.00	59.00
19.	TAILGATE INNER TRIM <i>de</i>	1	PC	180.00	180.00
20.	TAILGATE RUBBER <i>na</i>	1	PC	115.00	115.00
21.	TAILGATE GLASS MOULDING <i>na</i>	1	PC	70.00	70.00
22.	REAR BUMPER SIDE RETAINER <i>X nn</i>	2	PCS	30.00	60.00 X
23.	TAILGATE REFLECTOR LAMP <i>? X (no photo)</i>	2	PCS	421.00	842.00 X
24.	END PANEL GARNISH <i>de</i>	1	PC	115.00	115.00
25.	END PANEL ASSY <i>bu</i>	1	PC	415.00	415.00
26.	FLOOR PANEL <i>repair bt</i>	1	PC	910.00	910.00
27.	SPARE TYRE BOARD <i>de</i>	1	PC	425.00	425.00
28.	FLOOR PANEL SPONGE <i>cm</i>	1	PC	135.00	135.00
29.	REAR HYBRID BATTERY <i>X de</i>	1	PC	7,899.00	7,899.00
30.	REAR FENDER INNER TRIM <i>LH-de / RH-? X (no photo) nn</i>	2	PCS	310.00	620.00 X
31.	REAR FENDER LH <i>repair (no damage photo)</i>	1	PC	675.00	675.00 X
32.	REAR FENDER ARCH GARNISH <i>LH-de / RH-X (no photo) nn</i>	2	PCS	210.00	420.00 X
33.	TAILLAMP <i>su</i>	2	PCS	460.00	920.00
34.	HYBRID BATTERY CASING <i>? cut</i>	1	PC	280.00	280.00
35.	HYBRID BATTERY COOLING FAN <i>? X (no photo) nn</i>	1	PC	898.00	898.00 X
36.	HYBRID BATTERY COVER <i>? X (no photo) nn</i>	1	PC	346.00	346.00 X

9464
20%
7571.20

S/N-5000

LIST TOTAL S\$ 21,221.00
 20% DISCOUNT S\$ -4,244.20

16,976.80

SPECIAL NET ITEMS :

1.	REAR PARKING SENSOR <i>dis</i>	1	PC	200.00	200.00
2.	FRONT & REAR NUMBER PLATE <i>cut / mix</i>	2	PCS	50.00	100.00
3.	REAR WINDSCREEN SEALANT <i>na</i>	1	PC	40.00	40.00
4.	REAR CAMERA <i>X nn</i>	1	PC	200.00	200.00
5.	FRONT DRIVER SEAT TRIM ASSY - TBA <i>X nn</i>	1	PC		

S/N-340

J.P.M.

