



2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SKW4762G

Accident Date : 24/12/2020

Location : KPE TOWARDS ECP

Model: MAZDA 3
(30/10/2015)

3P: SJK7583L (CHINA TAPING)

S/No s.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper / <i>DU</i>	1,467.20	-	-
2	10 pcs	Rear bumper clips / <i>ARC</i>	-	30.00	<i>nett</i> -
3	<i>12</i> pcs	Rear bumper tow cover <i>(CRH) / BR</i>	52.40	<i>List</i>	-
4	1 pc	Rear bumper reinforcement / <i>BR</i>	733.50	-	-
5	<i>12</i> pcs	Rear bumper o/s & n/s reflector <i>(CRH) / BR</i>	137.80	-	-
6	2 pcs	Rear bumper o/s & n/s retainer / <i>BR</i>	98.80	<i>List</i> -	-
7	1 pc	Rear bumper sponge <i>X NN</i>	-	-	-
8	1 pc	Rear boot cover / <i>DU</i>	1,306.90	-	-
9	1 pc	Rear boot cover weatherstrip / <i>TN</i>	147.10	<i>List</i> -	-
10	1 pc	Rear boot cover "mazda 3" emblem / <i>ARC</i>	73.00	-	-
11	1 pc	Rear boot cover "sky active" emblem / <i>ARC</i>	86.90	-	-
12	1 pc	Rear boot cover emblem / <i>ARC</i>	91.50	-	-
13	1 pc	Rear end panel <i>X R</i>	-	-	-
14	1 pc	Rear end panel inner trim <i>X NN</i>	-	-	-
15	8 pcs	Rear end panel inner trim clips <i>X NN</i>	-	-	-
16	1 pc	Rear o/s & n/s tail-lamp <i>(CRH) / BR</i>	1,390.80	-	-
17	1 set	Rear reverse sensor / <i>BR</i>	-	280.00	-
18	1 pc	Front bumper / <i>BR</i>	1292.80	-	-
19	10 pcs	Front bumper clips / <i>ARC</i>	-	40.00	-
20	1 pc	Front bumper top cover / <i>CRH</i>	<i>112.00</i>	<i>List</i> -	-
21	8 pcs	Front bumper top cover clips / <i>ARC</i>	<i>10.00</i>	<i>nett</i> -	-
22	1 pc	Front bumper enforcement <i>X NAI</i>	606.80	-	-
23	1 pc	Front bumper sponge <i>X NAI</i>	-	-	-
24	1 pc	Front bumper tow cover <i>X NN</i>	59.00	-	-
25	2 pcs	Front bumper o/s & n/s fog lamp / <i>BR</i>	429.60	-	-
26	2 pcs	Front bumper o/s & n/s fog lamp bracket <i>X NAI</i>	-	-	-
27	1 pc	Front bumper o/s fog lamp top lamp (Garnish) / <i>CUT</i>	110.00	<i>List</i> -	-
28	1 pc	Front bumper grille (Lower) <i>X NAI</i>	-	-	-
29	2 pcs	Front bumper o/s & n/s retainer / <i>BR</i>	86.20	<i>List</i> -	-
30	1 pc	Front grille base / <i>BR</i>	263.30	<i>List</i> -	-
31	4 pcs	Front grille clips / <i>ARC</i>	-	16.00	<i>nett</i> -
32	2 pcs	Front grille moulding o/s & n/s(chrome) / <i>BR</i>	481.00	-	-
33	1 pc	Front grill top cover <i>X NAI</i>	456.30	-	-
34	1 pc	Front bonnet / <i>DU</i>	1456.90	-	-

1062 List /
537 List /
46.80 List /
1026 List /
55.20 List /
65.80 List /
62.20 List /
915 List /
200 nett /
1083 List /
30 nett /
330 List /
370 List /
1204 List /

35	1 pc	Front bonnet lock X NAI	-	-	-
36	2pcs	Front bonnet o/s & n/s hinges X NAI	-	-	-
37	2pcs	Front o/s & n/s head lamp / BR	5100.00	-	-
38	1 pc	Front support panel seal plate / TAI	162.50	List	-
39	1 pc	Front support panel lower garnish / TAI	125.30	List	-
40	2pcs	Front o/s & n/s support panel seal garnish / TAI	98.00	List	-
41	1 pc	Front radiator lower garnish / BR	225.00	List	-
42	1 pc	Front support panel / BR	860.00	-	-
Sub-Total:			17,398.60	366.00	0.00
			20%	0%	0%
After Less %:			13,918.88	366.00	0.00

4474 List ✓

468-40 List

Labour				
1		To dismantle, straighten & welding.	1,600.00	1000
2		To spray painting.	1,200.00	1000
3		To remove & replace rear reverse sensor.	80.00	30
4		To remove & replace rear boot lid.	80.00	50
5		To check wiring.	80.00	30
6		To re-seal anti-rust.	80.00	30
Sub-Total:			3,120.00	
Total:			17,404.88	
After Less 20%:			13,923.90	

List - 13,180
- 20%
10,544

Nett - 286

Labour - 2140
= 12,970

LIS - 10,376
= 10,400.90

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



AL 8778 1999
24 hr accident call

Mobil 1



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)
29/12/20, 10:00 am

WHL PL

L/S

Ry AL spy

7 days