

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/1018/2020/NS  
**DATE** : 29-Dec-20  
**WIP** : 64387

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.**

**YOUR INSURED VEH NO : SMP 1046 Z**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**

**TEL: 6841 0055 - FAX: 6256 4315**

**OWNER'S NAME** : MR VICTOR KOH  
**ADDRESS** : 80 BAYSHORE ROAD  
#05-27  
SINGAPORE 469992  
**TELEPHONE** : HP +65 90117477  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 1700006976-03  
**VEHICLE NO** : **SLP 2794 C**  
**MODEL CODE** : AUDI A4 SEDAN 1.4 TFSI S  
**MODEL YEAR** : 30/5/2017  
**ENGINE NO** : CVN 038676  
**CHASSIS NO** : WAUZZZF43HA162588  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 24-Dec-20  
**PLACE OF ACCIDENT** : 17E MOUNT SINAI RISE SINGAPORE 276913

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 2794 C**

| S/N                         | NATURE OF JOBS                                                                                                                                                                       | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                                                        | S/N \$ 280.00        |                            |
| 2                           | TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.                                                                             | S/N \$ 280.00        |                            |
| 3                           | TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, AND RHS FRONT DOOR. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 2,800.00          |                            |
| 4                           | TO RESPRAY THS FRONT FENDER AND RHS FRONT DOOR.                                                                                                                                      | \$ 2,300.00          |                            |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                       | S/N \$ 192.00        |                            |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                      | <b>: \$ 5,852.00</b> |                            |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 2794 C**

| S/N PARTS DESCRIPTION                  | QTY | DAMAGED PARTS & PRICES |         |
|----------------------------------------|-----|------------------------|---------|
|                                        |     | S/NETT                 | REMARKS |
| 1 FRONT FENDER - RH                    |     | \$ 758.00              |         |
| 2 FRONT FENDER ATTACHMENT PARTS        |     | \$ 200.00              |         |
| 3 FRONT FENDER BRACE - RH FRONT        |     | \$ 117.00              |         |
| 4 FRONT FENDER BRACKET - RH            |     | \$ 35.00               |         |
| 5 FRONT FENDER CLOSING ELEMENT - RH    |     | \$ 49.00               |         |
| 6 WHEEL HOUSING LINER - RH             |     | \$ 239.00              |         |
| 7 WHEEL HOUSING LINER ATTACHMENT PARTS |     | \$ 90.00               |         |
| 8 STONE CHIP GUARD                     |     | \$ 50.00               |         |
| 9 TOP FENDER LEDGE COVER - UPPER       |     | \$ 31.00               |         |
| 10 TOP FENDER LEDGE COVER - LOWER      |     | \$ 23.00               |         |
| 11 FRONT DOOR - RH                     |     | \$ 2,354.00            |         |
| 12 FRONT DOOR OUTER SEAL - RH          | NEC | \$ 203.00              |         |
| 13 BONDING AGENT                       | NEC | \$ 47.00               |         |
| 14 CLEANING SOLUTION                   | NEC | \$ 65.00               |         |
| 15 FRONT DOOR ATTACHMENT PARTS         |     | \$ 870.00              |         |
| 16 FRONT DOOR CATCH                    |     | \$ 104.00              |         |
| 17 TYRE PRESSURE DATA PLATE            |     | \$ 37.00               |         |
| 18 SUNDRIES                            |     | \$ 200.00              |         |
| <b>TOTAL SPARE PARTS</b>               | :   | <b>\$ 5,472.00</b>     |         |
| <b>TOTAL LABOUR CHARGES</b>            | :   | <b>\$ 5,852.00</b>     |         |
| <b>GRAND TOTAL</b>                     | :   | <b>\$ 11,324.00</b>    |         |

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT