



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 28.12.2020
Emailed : 20.01.2021, 5.20pm
Date Survey : 29.12.2020

VEHICLE NO : EB 120 S
MODEL : MIT ATTRAGE 1.2
WIP : 61249

Material	:	\$	<u>3,609.05</u>
Labour	:	\$	<u>2,385.00</u>
Sub-Total	:	\$	<u>5,994.05</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>5,694.05</u>
GST 7%	:	\$	<u>398.58</u>
Grand Total	:	\$	<u>6,092.63</u>
Finalise By/Date	:	<u>LOI / 20/01/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK _____ WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/12/2020	<table> <tr> <td>Cust No/Name</td><td>KCV16047/SEAH JIE-WEI, SHAUN (XIE JIEWEI</td></tr> <tr> <td>Reg No/Reg Date</td><td>EB120S / 22/09/2020</td></tr> <tr> <td>Date In/Mileage</td><td>29/12/2020/ 6396</td></tr> <tr> <td>Chassis/Package</td><td>MMBSTA13AMH000692</td></tr> <tr> <td>Engine No</td><td>3A92UJP7568</td></tr> <tr> <td>Make/Model</td><td>MIT/21MY ATTRAGE 1.2 CVT (E31)</td></tr> <tr> <td>Colour/Trim</td><td>P57 WINE RED PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV16047/SEAH JIE-WEI, SHAUN (XIE JIEWEI	Reg No/Reg Date	EB120S / 22/09/2020	Date In/Mileage	29/12/2020/ 6396	Chassis/Package	MMBSTA13AMH000692	Engine No	3A92UJP7568	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)	Colour/Trim	P57 WINE RED PEARL / BK BLACK
Cust No/Name	KCV16047/SEAH JIE-WEI, SHAUN (XIE JIEWEI														
Reg No/Reg Date	EB120S / 22/09/2020														
Date In/Mileage	29/12/2020/ 6396														
Chassis/Package	MMBSTA13AMH000692														
Engine No	3A92UJP7568														
Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)														
Colour/Trim	P57 WINE RED PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	19/01/2021/ 17:53	BLK	260 / AiTing	61249			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR RH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 675.00
E PNT98000 RESPRAY ON FRONT BUMPER, RH FRONT FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 700.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
E PNT88000 REPLACE FRONT SUPPORT PANEL								450.00
E PNT98000 RESPRAY FRONT SUPPORT PANEL								350.00
X EXC INSURANCE EXCESS								-300.00
X	HEADLAMP ASSY,RH				1.00	✓ 1697.00	23.00	1306.69
X	FACE,FR BUMPER				1.00	✓ 703.00	23.00	541.31
X	GRILLE ASSY,RADIATOR				1.00	✓ 597.00	23.00	459.69
X	MARK,THREE-DIA				1.00	✓ 53.00	23.00	40.81
X	GRILLE,FR UNDER				1.00	✓ 90.00	23.00	69.30
X	COVER,FR BUMPER GRILLE				1.00	✓ 157.00	23.00	120.89
X	GARNISH,FR BUMPER,RH				1.00	✓ 44.00	23.00	33.88
X	BRACKET,FR BUMPER SIDE,RH				1.00	✓ 8.00	23.00	6.16
X	GARNISH,FR BUMPER SIDE				1.00	✓ 120.00	23.00	92.40
X	GARNISH,FR BUMPER SIDE				1.00	✓ 168.00	23.00	129.36
X	TANK,WINDSHIELD WASHER				1.00	✓ 74.00	23.00	56.98
X	EMBLEM ECO				1.00	✓ 17.00	00.00	17.00

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/12/2020	Cust No/Name	KCV16047/SEAH JIE-WEI, SHAUN (XIE JIEWEI
	Reg No/Reg Date	EB120S / 22/09/2020
	Date In/Mileage	29/12/2020/ 6396
	Chassis/Package	MMBSTA13AMH000692
	Engine No	3A92UJP7568
	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/01/2021/ 17:53	BLK	260 / AiTing	61249

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X COVER,FR BUMPER	1.00	12.00	23.00	9.24
X RIVET,FR BUMPER	6.00	4.00	23.00	18.48
X PANEL ASSY,FR END	1.00	918.00	23.00	706.86
Z TEXT AIG OD CLAIM DOA : 28.12.20 SURVEYOR STEVE LKK 29.12.20 POLICY NO : 2070134781, REPAIR 06 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	3,609.05	Nett	5,694.05
Labour	2,325.00	7% GST on	398.58
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	6,092.63
Sundry/Others	-240.00		
Total(w/o GST)	5,694.05		

This is not an official tax invoice.
This is a computer generated document, no signature is required.

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: EB 120 S

<u>Materials</u>		<u>Cost (\$)</u>
1	Cover, Fr bumper	CRU 12.00 /
2	Rivet, Fr bumper (x6)	NEC 24.00 /
3	Panel assy, Fr end	DD 918.00 /
Total		954.00
Less 23%		219.42
Total Materials		734.58
<u>Labour</u>		<u>Cost (\$)</u>
1	Replace front support panel	450.00 /
2	Respray front support panel	350.00 /
Total Labour		800.00
Taxable Amount		1,534.58
7% GST		107.42
Grand total		<u>1,642.00</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

FB 120S

After Eng MUTEX VCI unit to Base all the send

2021.01.04

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	A13A 2021MY

All DTCs

2021.01.04

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition				
	MPI/GDI/DIESEL	KOSS_99880010		No DTCs					
	AT/CVT/A-MT/TC-SST	KOSS_99880010		No DTCs					
	4WS/Electric Power Steering	KOSS_99880010		No DTCs					
	ABS/ASC/ASTC/WSS	KOSS_99880010		No DTCs					
	SRS-AIR BAG	KOSS_99880010		No DTCs					
	Air Conditioner	KOSS_99880010		No DTCs					
	ETACS	KOSS_99880010		No DTCs					
	Meter	KOSS_99880010		No DTCs					
	Steering Angle Sensor	KOSS_99880010		Non-target System					
	KOS/OSS/IMMO/Keyless (with KOS)	KOSS_99880010		No DTCs					