

Our Job Ref No : 305441321

Date

31/12/20

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156

FINA	LIZAT	ION F	ORM							
Го	LKK					Fax:				
Attn	Ř	TAUFIKH								
Vehicle Reg No. : SHD8603S Date of Acc					e of Acci	dent: 28-Dec-20				
The s	survey	and e	stimates of	the repairs of th	e above-me	ntione	d vehicle	are a	as follows:-	
	The	epair	job shall bi	II to:	NTUC				CB5934B	
2.	The finalized amount shall be:									
	(a) Spare Parts after List discount									
	(b) Labour Charges								Y	
	Total for Part-By-Part Repair Cost									
	(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost								\$1,200.00 \$1,200.00	
	We sl	hali tro	eat the abo						is no reply from you	
	within 7 working days Thank you for your assistance.					We confirm the estimates and finalized amount				
	Signa Name Tel Fax		-	62148398 65468156			gnature me te :	_	taufikh таиfікн 14/1/21	
r O	fficial	Use O								
					Docur	ment		T		
	- 1	tem		Amount	Attac		Confirm	- 5 H	Remarks	

Ē

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	**************			
4. LTA Search Fee	\$7.49 / \$2.00			
Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:			
		 	_