



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20014672/Dtd3n2 Date: 05/07/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 5782K		Veh. Inspected	SHD 3193R
Policy No.			Coverage (\$)	0.00
Claim No.	C10008476/ST		Excess (\$)	0.00
Assign From	IVY RATILLA		Assign Date	29/12/2020
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40		c.c	1685
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	KMHLB41UMGU085465		Colour	BLUE
Odometer	58433 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/12/2020		Inspection Date	30/12/2020
Survey held at	BLK 9 SECTOR C# 01-42			
Repairer	BIFROST AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	