

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 Dec 2020 10:41	Clm Veh Model Changed	(204506) MAZDA 3 1.5 SEDAN L SP.6EAT (A).	[R] Lye Mun Onn
2	28 Dec 2020 10:41	Clm Created	Reg No: SKX5287A. Policy No: DMPCSNW00156322000. Acct Date: 2020/12/21. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Auto Insure Pte Ltd (HQ) (Woodlands)	[R] Lye Mun Onn
3	28 Dec 2020 10:46	Clm Submitted	2958.08.	[R] Lye Mun Onn
4	29 Dec 2020 14:59	Clm Registration Modified	Excess: -> 0.00. Excess Waived: -> 500.00.	[I] Jenny Lew
5	29 Dec 2020 14:59	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Jenny Lew
6	29 Dec 2020 14:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/01/08	[I] Jenny Lew
7	29 Dec 2020 14:59	Adj Mandate Set	Approved:0.00.	[I] Jenny Lew
8	29 Dec 2020 15:59	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	29 Dec 2020 22:02	Adj Adjuster Assigned	[None] -> OI SUN PIN	[A] Nivitha Govindasamy
10	31 Dec 2020 10:56	Adj Rpt Initiated		[A] SHIAU CHAN
11	31 Dec 2020 10:57	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/01/08	[A] SHIAU CHAN
12	31 Dec 2020 10:58	Adj Mandate Request	Cur.Req:2703.31:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	04 Jan 2021 10:28	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/01/08. Mandate Remarks: Please proceed to authorize repairs UP TO \$2,703.31.	[I] Alfred Toh
14	04 Jan 2021 10:28	Adj Mandate Set	Approved:2703.31:Please proceed to authorize repairs UP TO \$2,703.31.	[I] Alfred Toh

Date From   
 Date To   
 Audit Type None  Go

ACTIVITY

[29/12/2020 17:05] Nivitha Govindasamy:
 Please be informed that repairer agreed to survey on 30/12/2020.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2656815	28 Dec 2020 10:41:35	OD/TP Case (Repairer)	Motor	Auto Insure Pte Ltd (HQ)	Auto Insure Pte Ltd (HQ) (Woodlands)	SKX5287A		xx.xx
2657896	31 Dec 2020 10:56:00	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKX5287A		11.00

