



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072			
			Document No.					
			0					
			Document Date					
			28/12/2020					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	0	20594	67/DS/SJD1178A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH60J004852		8ARZ164699	60	Sam San Joi	28/12/2020 17.25		--/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ1054L ACC DATE:26/12/2020 DRIVE IN:28/12/2020 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:						30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS						183.18
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR						180.00
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST						180.00
5	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR						360.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT)- TAILGATE, REAR EN D PANEL						120.00
7	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS						462.00
8	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM						350.00
9	B	BP-LAB2 REMOVE & INISTALL REAR REVERSE CAMERA						180.00
10	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE						360.00
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle				Less		
				Parts Labour Sublet Lubrication/Fluid Others		Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072		
			Document No. 0				
			Document Date 28/12/2020				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	0	20594	67/DS/SJD1178A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH60J004852		8ARZ164699	60	Sam San Joi	28/12/2020 17.25		--/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00	
12	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				4320.00	
13	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				2950.00	
14	1	T52159-48933 COVER, RR BUMPER	1.00	904.00		904.00	
15	2	T52156-48050 SUPPORT, RR BUMPER	1.00	82.70		82.70	
16	3	T52155-48050 SUPPORT, RR BUMPER	1.00	82.70		82.70	
17	4	T52169-48100 COVER, RR BUMPER,	1.00	466.00		466.00	
18	5	S52161-0K040 CLIPS	10.00	4.10		41.00	
19	6	T52163-48050 PLATE, RR BUMPER, RH	1.00	98.20		98.20	
20	7	T52615-48230 ABSORBER, RR BUMPER	1.00	122.60		122.60	
21	8	L81920-48012 REFLECTOR ASSY,	1.00	59.80		59.80	
22	9	T81910-48012 R/RR BPR REFLECTOR ASSY,	1.00	59.80		59.80	
23	0	T58307-48120 PANEL SUB-ASSY, BODY	1.00	1006.40		1006.40	
24	1	T48691-48030 DAMPER, SUSPENSION	1.00	1343.10		1343.10	
25	2	T58311-42132 PAN, RR FLOOR	1.00	818.10		818.10	
26	3	T64716-48020 C0 COVER, DECK TRIM, RR	1.00	438.30		438.30	
27	4	T58410-48120 C0 BOARD ASSY, DECK	1.00	885.50		885.50	
28	5	T58409-48080 C0 BOARD SUB-ASSY,	1.00	193.40		193.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072			
			Document No. 0					
			Document Date 28/12/2020					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	0	20594	67/DS/SJD1178A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH60J004852		8ARZ164699	60	Sam San Joi	28/12/2020 17.25 --/--/----		0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
29	6	T58408-48090 C0 BOARD SUB-ASSY,			1.00	156.50		156.50
30	7	T64779-48060 TRAY, SPARE WHEEL			1.00	782.20		782.20
31	8	T64997-48010 BOX, DECK FLOOR, LH			1.00	640.50		640.50
32	9	T64995-48010 BOX, DECK FLOOR, RH			1.00	444.20		444.20
33	0	T64740-48120 C0 PANEL ASSY, DECK			1.00	718.00		718.00
34	1	T64730-48120 C0 PANEL ASSY, DECK			1.00	718.00		718.00
35	2	T67005-48350 PANEL SUB-ASSY, BACK			1.00	2378.00		2378.00
36	3	T67881-48070 WEATHERSTRIP, BACK			1.00	441.30		441.30
37	4	T68105-48905 GLASS SUB-ASSY, BACK			1.00	1218.20		1218.20
38	5	T75575-48040 MOULDING, BACK			1.00	51.90		51.90
39	6	T67750-48010 C0 BOARD ASSY, BACK			1.00	578.50		578.50
40	7	T69350-48063 LOCK ASSY, BACK DOOR			1.00	974.00		974.00
41	8	T69430-48030 STRIKER ASSY, BACK			1.00	41.00		41.00
42	9	T69321-48050 COVER, BACK DOOR			1.00	31.50		31.50
43	0	T90975-02071 EMBLEM,SYMBOL			1.00	57.30		57.30
44	1	T75442-48140 PLATE, BACK DOOR			1.00	73.70		73.70
45	2	SPZQ31-13020 Badge Assy, Engine Mark RHS			1.00	17.52		17.52
46	3	T89997-30100 ANTENNA, ELECTRICAL			1.00	72.00		72.00
47	4	T89341-58060 A0 SENSOR, ULTRASONIC,			2.00	481.90		963.80
48	5	T89348-58070 A0 RETAINER, ULTRASONIC			2.00	21.30		42.60
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No. S1000020 / TPCLAIM		Customer Details			
THIRD PARTY CLAIM			Document No. 0		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072			
			Document Date 28/12/2020					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	0	20594	67/DS/SJD1178A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH60J004852		8ARZ164699	60	Sam San Joi	28/12/2020 17.25		--/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
49	6	T89348-58120 RETAINER, ULTRASONIC			4.00	16.00		64.00
50	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00		216.00
51	8	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 27,337.50		
				Parts 17,482.32		GST 7.00% 1,913.63		
				Labour 9,142.00				
				Sublet 713.18		Less 0.00		
				Lubrication/Fluid 0.00				
				Others 0.00		Amount Due 29,251.13		

Customer Copy