



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details			
EQ Insurance Company Ltd 5 Maxell Road #17-00 Tower Block MND Complex Singapore 069110			S1000021 / ICEQI1		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072			
			Document No. 39011385					
			Document Date 22/01/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	12742	20594	67/DS/SJD1178A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH60J004852		8ARZ164699	30	Sam San Joi	28/12/2020 17.22		08/01/2021 8.49	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ1054L ACC DATE:26/12/2020 DRIVE IN:28/12/2020 DATE-IN:04/01/2021 DATE SURVEY:04/01/2021 NO OF REPAIR DAYS:6 DAYS BY:ADRIAN(LKK)						30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS			0619			183.18
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR			BP01			180.00
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST			BP01			180.00
5	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR			BP01			360.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT)- TAILGATE						60.00
7	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS			BP01			462.00
8	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM			0741			350.00
9	B	BP-LAB2 REMOVE & INISTALL REAR REVERSE CAMERA			BP01			180.00
10	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE			BP01			360.00
11	S	BP-SUBLET TO RESET ECU AND REPROGRAMME			0742			180.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details			
EQ Insurance Company Ltd 5 Maxell Road #17-00 Tower Block MND Complex Singapore 069110			S1000021 / ICEQI1		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072			
			Document No. 39011385					
			Document Date 22/01/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	12742	20594	67/DS/SJD1178A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH60J004852		8ARZ164699	30	Sam San Joi	28/12/2020 17.22		08/01/2021 8.49	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
12	B	BP-LAB2	REPLACE REAR ACCIDENT DAMAGED PARTS			BP01		2160.00
13	I	BP-RES2	STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS			*		1770.00
14	1	T52159-48933	COVER, RR BUMPER			1.00	904.00	904.00
15	2	T52156-48050	SUPPORT, RR BUMPER			1.00	82.70	82.70
16	3	T52155-48050	SUPPORT, RR BUMPER			1.00	82.70	82.70
17	4	T52169-48100	COVER, RR BUMPER,			1.00	466.00	466.00
18	5	S52161-0K040	PIECE, RR BUMPER			10.00	4.10	41.00
19	6	T67005-48350	PANEL SUB-ASSY, BACK G			1.00	2378.00	2378.00
20	7	T68105-48905	GLASS SUB-ASSY, BACK			1.00	1218.20	1218.20
21	8	T75575-48040	MOULDING, BACK			1.00	51.90	51.90
22	9	T90975-02071	EMBLEM,SYMBOL			1.00	57.30	57.30
23	0	T75442-48140	PLATE, BACK DOOR			1.00	73.70	73.70
24	1	SPZQ31-13020	Badge Assy, Engine Mark RHS (AUD)			1.00	17.52	17.52
25	2	T89348-58070 A0	RETAINER, ULTRASONIC			2.00	21.30	42.60
26	3	T89348-58120	RETAINER, ULTRASONIC			4.00	16.00	64.00
27	4	T21000-20	SIKA 210002-0 TACK GO! (BLACK) SG			2.00	108.00	216.00
28	5	T21000-22	SIKA 210002-2 G+P 207 ADHESIVE PRIMER			1.00	200.00	200.00
29	6	T51931-47020	CARRIER, SPARE			1.00	20.80	20.80
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
					Parts		Less	
					Labour			
					Sublet			
					Lubrication/Fluid			
					Others		Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details				Account No.		Customer Details			
EQ Insurance Company Ltd 5 Maxell Road #17-00 Tower Block MND Complex Singapore 069110				S1000021 / ICEQI1		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072			
				Document No. 39011385					
				Document Date 22/01/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	12742	20594	67/DS/SJD1178A		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTEKB3GH60J004852		8ARZ164699	30	Sam San Joi	28/12/2020 17.22		08/01/2021 8.49		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
30	7	T52615-48230 ABSORBER, RR BUMPER			1.00	122.60		122.60	
31	8	T48691-48030 DAMPER, SUSPENSION			1.00	1343.10		1343.10	
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd						13,837.30			
		Please acknowledge receipt of vehicle		Parts		GST 7.00%			
				Labour		968.61			
				Sublet		Less			
				Lubrication/Fluid		0.00			
				Others		Amount Due			
						14,805.91			

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details			
EQ Insurance Company Ltd 5 Maxell Road #17-00 Tower Block MND Complex Singapore 069110			S1000021 / ICEQI1		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072			
			Document No. 39011385					
			Document Date 22/01/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	12742	20594	67/DS/SJD1178A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH60J004852		8ARZ164699	30	Sam San Joi	28/12/2020 17.22		08/01/2021 8.49	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ1054L ACC DATE:26/12/2020 DRIVE IN:28/12/2020 DATE-IN:04/01/2021 DATE SURVEY:04/01/2021 NO OF REPAIR DAYS:6 DAYS BY:ADRIAN(LKK)						30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS			0619			183.18
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR			BP01			180.00
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST			BP01			180.00
5	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR			BP01			360.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT)- TAILGATE						60.00
7	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS			BP01			462.00
8	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM			0741			350.00
9	B	BP-LAB2 REMOVE & INISTALL REAR REVERSE CAMERA			BP01			180.00
10	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE			BP01			360.00
11	S	BP-SUBLET TO RESET ECU AND REPROGRAMME			0742			180.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details				Account No.		Customer Details				
EQ Insurance Company Ltd 5 Maxell Road #17-00 Tower Block MND Complex Singapore 069110				S1000021 / ICEQI1		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072				
				Document No. 39011385						
				Document Date 22/01/2021						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks			
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	12742	20594	67/DS/SJD1178A			
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On			
JTEKB3GH60J004852		8ARZ164699	30	Sam San Joi	28/12/2020	17.22	08/01/2021	8.49		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount	
12	B	BP-LAB2	REPLACE REAR ACCIDENT DAMAGED PARTS				BP01			2160.00
			STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS							
13	I	BP-RES2	RESPRAY JOB ON REAR ACCIDENT AFFECTED AR				*			1770.00
		EAS								
14	1	T52159-48933	COVER, RR BUMPER				1.00	904.00		904.00
15	2	T52156-48050	SUPPORT, RR BUMPER				1.00	82.70		82.70
16	3	T52155-48050	SUPPORT, RR BUMPER				1.00	82.70		82.70
17	4	T52169-48100	COVER, RR BUMPER,				1.00	466.00		466.00
18	5	S52161-0K040	PIECE, RR BUMPER				10.00	4.10		41.00
19	6	T67005-48350	PANEL SUB-ASSY, BACK G				1.00	2378.00		2378.00
20	7	T68105-48905	GLASS SUB-ASSY, BACK				1.00	1218.20		1218.20
21	8	T75575-48040	MOULDING, BACK				1.00	51.90		51.90
22	9	T90975-02071	EMBLEM,SYMBOL				1.00	57.30		57.30
23	0	T75442-48140	PLATE, BACK DOOR				1.00	73.70		73.70
24	1	SPZQ31-13020	Badge Assy, Engine Mark RHS (AUD)				1.00	17.52		17.52
25	2	T89348-58070 A0	RETAINER, ULTRASONIC				2.00	21.30		42.60
26	3	T89348-58120	RETAINER, ULTRASONIC				4.00	16.00		64.00
27	4	T21000-20	SIKA 210002-0 TACK GO! (BLACK) SG				2.00	108.00		216.00
28	5	T21000-22	SIKA 210002-2 G+P 207 ADHESIVE PRIMER				1.00	200.00		200.00
29	6	T51931-47020	CARRIER, SPARE				1.00	20.80		20.80
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary			Total		
			Please acknowledge receipt of vehicle		Parts			Less		
					Labour					
					Sublet					
					Lubrication/Fluid					
					Others			Amount Due		

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details			
EQ Insurance Company Ltd 5 Maxell Road #17-00 Tower Block MND Complex Singapore 069110			S1000021 / ICEQI1		Mr Chong Yeow Hwee (Zhang Yaohui) 6A Lincoln Road #21-13 Singapore 308366 Mobile: 91472072			
			Document No. 39011385					
			Document Date 22/01/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASU60R	ANTGT P1	30/07/2019	SJD1178A	12742	20594	67/DS/SJD1178A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH60J004852		8ARZ164699	30	Sam San Joi	28/12/2020	17.22	08/01/2021 8.49	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
30	7	T52615-48230 ABSORBER, RR BUMPER			1.00	122.60		122.60
31	8	T48691-48030 DAMPER, SUSPENSION			1.00	1343.10		1343.10
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 13,837.30		
		Please acknowledge receipt of vehicle		Parts 7,382.12 Labour 5,742.00 Sublet 713.18 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 968.61 Less 0.00 Amount Due 14,805.91		

Company Copy