

Ulu Cecilia

Not Asst
Lm
30/12/20 1/2 # 4800
5 days



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

Christina

ESTIMATION QUOTE

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #04/#05
IOB BUILDING
SINGAPORE 049711
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SMD8924G
MAKE MODEL : MIT LANCER
REFERENCE : 1AP-202012-48
DOA : 26-Dec-20
CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

nett item

ITEMS	QTY	LIST PRICE (\$)	REMARKS
*REAR BOOT	1	\$ 793.00	DD ✓
*REAR BOOT TAIL LIGHT LH / RH	2	\$ 464.00	u r X
*REAR BOOT EMBLEM	1	\$ 147.00	net ✓
*REAR BOOT LOGO LANCER	1	\$ 152.00	net ✓
*REAR BOOT LOGO EX	1	\$ 139.00	net ✓
*REAR BOOT LOGO GT	1	\$ 145.00	net ✓
*REAR BOOT LOCK	1	\$ 167.00	u r X
*REAR BOOT HINGE LH / RH	2	\$ 368.00	u r X
*REAR BOOT INNER STOPPER	1	\$ 115.00	u r X
*REAR BOOT ABSORBER LH / RH	2	\$ 322.00	u r X
*REAR BOOT INNER RUBBER MOULDING	1	\$ 266.00	u r X
*REAR BOOT INNER INSULATOR	1	\$ 403.00	u r X
*REAR TAIL LAMP LH / RH	2	\$ 1,108.00	u r X
*REAR END PANEL	1	\$ 606.00	DD ✓
*REAR BUMPER REINFORCEMENT	1	\$ 385.00	BMT ✓
*REAR END PANEL TOP GARNISH	1	\$ 249.00	Twi ✓
*REAR INNER TRIM BOARD LH / RH	2	\$ 446.00	net ✓
*REAR SPARE TYRE BOARD	1	\$ 295.00	u r X
*REAR BOOT BRAKE LIGHT TOP CENTER	1	\$ 336.00	l r o ✓
*REAR BUMPER	1	\$ 815.00	net ✓
*REAR BUMPER SIDE RETAINER LH / RH	2	\$ 230.00	net ✓
*REAR BUMPER TOWING COVER	1	\$ 120.00	net ✓
*REAR BUMPER REFLECTOR LH / RH	1	\$ 244.00	u r o ✓
*REAR SPARE TYRE TRUNK	1	\$ 521.00	u r X

\$ 10,558.00
 LESS 10% \$ 1,055.80
 SUBTOTAL \$ 9,502.20
 BALANCE C/F \$ 9,502.20

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 9,502.20	
*REAR BOOT INNER CLIP	1	\$ 50.00	net 30
*REAR BOOT SPOILER	1	\$ 800.00	210 500

ESTIMATION QUOTE

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL STREET #04/#05
 IOB BUILDING
 SINGAPORE 049711
 ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SMD8924G
 MAKE MODEL : MIT LANCER
 REFERENCE : 1AP-202012-48
 DOA : 26-Dec-20
 CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
*REAR BUMPER CLIPS	1	\$ 50.00	na ✓
*REAR NUMBER PLATE WITH HOLDER	1 SET	\$ 100.00	no 40
*REVERSE CAMERA	1 SET	\$ 300.00	shld ✓
*REVERSE SENSOR	1 SET	\$ 200.00	shld ✓
*EXHAUST	1	\$ 2,200.00	R X

SUBTOTAL \$ 3,700.00

BALANCE C/F \$ 10,602.20

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
--------	------	-----------------	---------

BALANCE B/F \$ 10,602.20

TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING - REAR	1	\$ 200.00	30
TO REMOVE AND REFIT REAR EXHAUST TO FACILITATE THE REPAIR	2	\$ 300.00	60
TO REMOVE AND REFIT SPARE TYRE PANEL TO FACILITATE THE REPAIR	3	\$ 150.00	80
TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR	4	\$ 250.00	
TO REMOVE, REFIT ^{replace} AND TEST REVERSE SENSOR	5	\$ 200.00	50
TO TRANSFER BOOTLID COMPONENT FROM OLD TO NEW	6	\$ 200.00	60
PANEL BEATING ON AFFECTED AREA	7	\$ 2,000.00	600
SPRAY PAINTING	8	\$ 2,000.00	900
APPLY ANTI RUST ON AFFECTED AREA	9	\$ 150.00	60

SUBTOTAL \$ 5,450.00

GRAND TOTAL \$ 15,152.20

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3387-70
 100
 P-304893
 S.N-1120.00
 L-1840.00
 600893
 4800.